Tree Cassyn

Damp. Timber. Moisture Investigations.

TREE CASSYN BUILDING SCIENCE SERIES

TC-06

Rising Damp in Traditional Buildings

Understanding how buildings behave.

EVIDENCE-LED GUIDANCE FOR TRADITIONAL BUILDINGS ON THE ISLE OF MAN



Contents

Foreword 2

PART ONE - UNDERSTANDING THE MECHANISM

1. What is rising damp? 3
2. Porosity is not the same as a capillary pathway 6
3. What controlled experiments tell us 8

PART TWO - WHEN THE WALL BECOMES COMPLICATED

4. The traditional solid wall 10
5. The surface and the wall behind it 14

PART THREE - THE SAME SYMPTOM, DIFFERENT JOURNEYS

6. Low-level damp does not identify its source 17
7. Other routes to low-level moisture 21
8. When water travels before we see it 25

PART FOUR - DIAGNOSING THE WALL

9. From moisture reading to moisture diagnosis 29
10. Following the water 32

PART FIVE - THE MANX BUILDING

11. Does location change the risk? 36
12. Was there really no damp-proof course? 40

PART SIX - TREATMENT

13. How does a chemical damp-proof course actually work? 43
14. Injection, replastering and the causation problem 46
15. Electro-osmosis and other electrical approaches 48

PART SEVEN - BRINGING THE EVIDENCE TOGETHER

16. When is rising damp the reasonable diagnosis? 50
17. A practical differential diagnosis 53

Closing Thoughts 57
Glossary of Key Terms 60
Further Reading & Sources 63
About the Tree Cassyn Building Science Series 66
Important Note 66



Foreword

Few forms of dampness generate as much disagreement as rising damp.

At one extreme, it is sometimes treated almost as an inevitable consequence of owning an older building without a modern damp-proof course. At the other, it is occasionally dismissed as something that barely exists at all.

Neither position is particularly helpful. The useful question sits between them.

Rising damp is real. Water can move upwards through porous materials by capillary action, and controlled experiments have demonstrated that it can rise considerable distances through masonry when the necessary conditions are present.

The more difficult question is not whether rising damp can occur. It is whether rising damp is the cause of the moisture found in a particular wall. That is the question that matters during an investigation.

That distinction matters because low-level dampness is not unique to rising damp. Rain penetration, defective drainage, leaking services, condensation, salts, changes to external ground levels and moisture moving through other parts of the building can all produce dampness at or near the base of a wall. More than one mechanism may also be operating at the same time.

The materials themselves add another layer of complexity. A regular brick wall built with continuous mortar beds is very different from a 500 or 600 mm traditional stone wall comprising irregular stones, lime mortar, rubble, voids, cracks and generations of repair. The plaster on the face of that wall may behave differently again.

This guide therefore does not set out to argue that rising damp is either commonplace or negligible. Instead, we will follow the evidence.

We will look at what happens when researchers deliberately create rising damp in controlled masonry walls. We will compare brick, stone and rubble construction. We will examine what porosity actually means, how water moves from one material into another, how plaster and mortar can change its route, and what happens when liquid water enters a wall from somewhere other than the ground.

Later, we will consider what all of this means when a surveyor places a moisture meter against a wall and records high readings near the floor.

Modern professional guidance, including the Joint Position Statement on moisture investigation in traditional buildings and BS 6576, places considerable emphasis on diagnosis before treatment. Rather than simply repeating that advice, this guide aims to explain **why that caution exists**. [15][16]

The starting point is the science.



PART ONE - UNDERSTANDING THE MECHANISM
CHAPTER 1

What is rising damp?

Rising damp sounds as though it simply describes where dampness is found. It does not. It describes a very particular moisture journey.

At its simplest, rising damp is **ground-derived liquid water moving upwards through a wall by capillary action**.

There are two important parts to that definition. The first is the **source**: the water comes from the ground. The second is the **transport mechanism**: it moves upwards through the building fabric by capillary action.

Those two conditions distinguish rising damp from other forms of moisture movement. If rainwater enters a wall around a defective window and subsequently moves through the masonry by capillary action, capillary movement is taking place - but it is not rising damp. Likewise, if water vapour condenses inside a wall and the resulting liquid water subsequently travels through mortar or plaster, capillary transport may again occur without the original water having come from the ground.

Source and transport are related, but they are not the same question.

Capillary action in everyday terms

A familiar example of capillary action is the edge of a paper towel touching spilled water. The whole towel does not need to be submerged. Water is drawn into its fine internal structure and can travel upwards and sideways through it.

Porous building materials can behave in a broadly similar way. Brick, mortar, many stones and plasters contain networks of tiny pores. Where those pores are sufficiently small and sufficiently well connected, water can be drawn into them.

The interaction between water and the surface of the pore creates capillary suction. In sufficiently fine pores that force can overcome gravity, allowing water to move upwards. But this does not mean that water simply rises indefinitely.

Several competing processes are occurring at the same time. Water may be drawn upwards from below. Gravity acts downwards. Water evaporates from the surfaces of the wall. The amount of water available at the base may change. Temperature, humidity and air movement alter the rate at which the wall can dry.

Eventually, under sufficiently stable conditions, a balance may develop between the amount of water entering the wall and the amount leaving it. Rising damp is therefore better understood as a **dynamic moisture system** than as a fixed line of dampness climbing a wall.

Water must be available in the first place

Capillary action cannot draw water from a source that does not exist. This sounds obvious, but it is fundamental.

A building without a modern damp-proof course does not automatically have rising damp. There must also be sufficient liquid water in contact with, or accessible to, the base of the construction.



That supply may come from shallow groundwater, saturated soil, perched water, poor drainage or some other persistent source. It will not necessarily remain constant throughout the year. Ground conditions after months of winter rainfall may be quite different from those at the end of a dry summer.

A pathway needs a source.

What controls how high water can rise?

So what decides how far the water gets? It is tempting to reduce the answer to one factor - the ability of the wall to "suck" water upwards. Real behaviour is more complicated.

- the size and shape of the pores;
- how well those pores connect;
- the amount and persistence of water available;
- the materials making up the wall;
- the interfaces between those materials;
- the thickness of the wall;
- the rate of evaporation;
- temperature and relative humidity;
- salts; and
- the finishes applied to the wall.

This explains why two apparently similar walls may behave very differently. It also explains why laboratory tests on an individual brick or stone cannot automatically tell us how an entire historic wall will behave.

Rising damp is not in scientific doubt

Controlled research has deliberately placed masonry in contact with liquid water and measured that water moving upwards through the construction.

> RESEARCH SPOTLIGHT
>
> ### When the source is known
>
> In a long-running full-scale experiment published in 2021, researchers built large clay-brick and lime-mortar walls, supplied water continuously at their bases and monitored them for **600 days**. Moisture fronts eventually reached approximately 1.68 m in the solid wall and 1.92 m in the cavity wall. [3]
>
> The importance of the experiment is not simply the height reached. The researchers knew the water source because they supplied it themselves; they knew the construction because they built the walls; and they could exclude gutters, plumbing, rainfall and other unknown sources.

Natural stone can also transport water upwards. Controlled work using tuff, Lecce stone and Carparo produced substantial but different capillary-rise heights, showing that pore structure and connectivity matter greatly. [5]



So the question for this guide is not whether capillary rise exists. It plainly does. The interesting work begins when we ask whether a particular old wall actually possesses the source and connected pathway required to produce it.

CHAPTER TAKEAWAY

- Rising damp is a specific mechanism: ground-derived liquid water moving upwards by capillary action.
- A wall without a modern DPC does not automatically have rising damp; sufficient liquid water must also be available at its base.
- The height and rate of rise depend on water supply, pore structure, connectivity, evaporation and the complete wall assembly.
- Controlled experiments prove that substantial rising damp can occur when the necessary conditions are present.



CHAPTER 2

Porosity is not the same as a capillary pathway

A porous wall is not automatically a capillary highway.

Traditional buildings are often described as porous. That is true. But porosity by itself tells us only that void space exists; it does not tell us whether those voids join up into a route through which liquid water can travel.

For meaningful capillary movement, those spaces have to connect in a useful way.

From pores to pathways

Imagine two materials containing the same total volume of tiny holes. In the first, almost every hole connects with the next. In the second, most holes are isolated pockets. Both may have similar porosity, yet only one provides an effective route through which water can travel any meaningful distance.

That distinction is **pore connectivity**. For capillary moisture to travel through a wall, the water needs more than pores. It needs a sufficiently continuous route from one pore to another.

Porosity → pore connectivity → hydraulic continuity → capillary pathway.

A wall is not necessarily one material

Consider a simple laboratory block of stone. It may possess one relatively consistent pore structure. Now consider a wall made from stone, mortar, another stone, another mortar joint, rubble, a crack, a void, more mortar, perhaps a later cement repair, and eventually plaster on the room side.

The question is no longer merely **"Is the stone porous?"** It becomes: **Can water move successfully from one pore network into the next, across every interface required to complete the journey?**

Interfaces matter

Research into brick-and-mortar assemblies has demonstrated that even two porous materials placed directly against one another do not necessarily behave as a single continuous capillary system. The interface between them can create measurable resistance to moisture transfer. [6][7]

Two capillary-active materials do not automatically create one continuous capillary pathway.

Now think about what this means for traditional rubble masonry. Instead of a few regular brick–mortar interfaces, there may be hundreds or thousands of irregular contacts between stones, old lime mortar, rubble fragments, fines, cracks and voids.

Some may transport moisture readily. Some may slow it. Some may interrupt it. Others may create preferential routes through which water moves more readily than through the surrounding materials. The result is unlikely to be uniform.

Heterogeneity works in both directions

A heterogeneous wall does **not** automatically prevent rising damp. Water may find highly effective preferential pathways. A continuous mortar joint might transport water readily even where the stones beside it do not. A



crack or interface may provide another route. A plaster layer might provide a comparatively continuous pathway across materials whose internal connections are much less regular.

So heterogeneity can interrupt moisture movement, but it can also redirect and concentrate it.

The useful question is not "Is this rubble wall porous?" but "What are the actual liquid-water pathways in this wall?"

Why this matters diagnostically

Imagine placing an electrical moisture meter against the plastered face of a 550 mm rubble wall. The instrument is interacting primarily with the material at or close to its electrodes. It is not directly measuring the hydraulic continuity of half a metre of heterogeneous masonry behind it.

If the plaster provides a different moisture pathway from the core, the surface condition may not faithfully describe the wall behind. We will return to this later. For now, one principle is enough: **the material we can see and measure at the surface is not necessarily representative of the complete construction behind it.**

CHAPTER TAKEAWAY

- Porosity tells us that pore space exists; it does not tell us whether that pore space forms a continuous route for liquid water.
- Interfaces between porous materials can themselves resist liquid-water transfer.
- Heterogeneity can interrupt, redirect or concentrate moisture movement; it does not automatically prevent rising damp.
- A surface measurement cannot be assumed to represent the hydraulic behaviour of the complete wall behind it.



CHAPTER 3

What controlled experiments tell us

Controlled studies give us something real buildings rarely do: certainty about the source. When the materials and construction are known as well, we can see what genuine rising damp does without first having to guess where the water came from.

Before examining complicated historic walls, it is useful to begin with situations where researchers control as many variables as possible. This gives us something akin to a scientific baseline.

Lesson 1 - rising damp can be substantial

The 600-day brick-wall experiment is a particularly useful example. Two large walls were built from clay blue brick and lime mortar and continuously supplied with water. Both developed substantial rising moisture, with fronts approaching two metres after 600 days. [3]

So the suggestion that capillary moisture can only rise a few centimetres is plainly not universally correct. Under conducive conditions, it can rise much further.

Lesson 2 - the material matters

Natural-stone experiments tell us something equally useful. Tuff, Lecce stone and Carparo all transported water upwards, but to different heights. Their pore structures were different. Some pore sizes generated stronger suction, others allowed easier flow, and the final behaviour reflected the balance between suction, connectivity, permeability and evaporation. [5]

Lesson 3 - smaller pores do not simply mean “more damp”

Very fine pores can exert strong capillary suction, but the same narrow pathways can also offer significant resistance to flow. Larger pores may permit easier bulk movement in some circumstances but generate weaker capillary rise. The behaviour cannot be reduced to one number such as total porosity.

Lesson 4 - the wall assembly matters, not just the ingredients

As soon as brick meets mortar, or stone meets lime, another variable appears: the interface between them. Controlled research has shown that these interfaces can materially alter liquid-water movement. [6][7]

So even where Material A transports water and Material B transports water, it does not automatically follow that **A + B** transports water as one uninterrupted system.

Lesson 5 - controlled experiments have one enormous advantage

They know where the water came from. In a laboratory rising-damp experiment, the source, material and wall construction are known, and other water sources can largely be excluded.

In a real building we may instead find a cracked external render, an old roof, hidden plumbing, blocked drainage, altered ground levels, salts, a cold wall, high indoor humidity, an unknown wall core and 150 years of repairs. The low-level moisture reading may look similar. The certainty about its source is completely different.



RESEARCH SPOTLIGHT

Why the laboratory matters

Controlled brick and stone experiments provide a **positive control**. They show us what genuine ground-fed capillary rise can do when the source and construction are known.

The purpose is not to make a historic building behave like a laboratory wall. It is to give us a baseline against which the much more complicated evidence from real walls can be compared.


CHAPTER TAKEAWAY

- Controlled research demonstrates that substantial rising damp can occur in both brick and natural stone.
- Material type, pore structure, interfaces, construction and evaporation all change the outcome.
- A real historic wall contains far more unknowns than a laboratory specimen.
- The laboratory proves the mechanism; the survey must still establish whether that mechanism explains the wall in front of us.



PART TWO - WHEN THE WALL BECOMES COMPLICATED
CHAPTER 4

The traditional solid wall



A traditional wall is not a laboratory block. It is a composite moisture system whose internal geometry may be irregular, aged and partly unknown.

A solid wall that has stood for 150 years may contain several different stones, lime mortar, rubble, fines, voids, cracks, later cement repairs and multiple generations of plaster or render.

Some parts may absorb water readily. Others may absorb very little. Some interfaces may transfer liquid water effectively. Others may interrupt its movement.

The result is not one material. It is a composite moisture system.

From regular masonry to rubble

A regular brick wall has a clear geometry. Bricks repeat and mortar beds are comparatively continuous. Traditional stonework is different. Coursed stone retains some regularity, but random rubble walls can contain large facing stones, smaller packing stones, lime mortar, loose rubble, fines, voids and irregular joints across a thickness of 500 or 600 mm.

For liquid water to rise through the complete assembly, it needs a sufficiently continuous route through that three-dimensional network. This does not mean rubble walls cannot carry rising damp. They can. It means their behaviour cannot safely be assumed from the porosity of one stone or one mortar sample.

RESEARCH SPOTLIGHT

Bath - a 600 mm rubble wall that did not behave as predicted

Researchers from the University of Bath and Historic England monitored a historic rubble-filled wall for approximately three years while investigating the effect of installing an impermeable floor. A theoretical capillary model suggested moisture might rise roughly 800–1,200 mm. The monitored wall did not show that predicted behaviour. [2]

Inspection identified large voids and discontinuities. The study therefore demonstrated something more useful than “rubble walls do not suffer rising damp”: **a real heterogeneous wall may behave very differently from an idealised interconnected capillary model.**

The study also tested a familiar conservation proposition: that restricting evaporation through an old floor would “drive” ground moisture into the adjacent wall. After a vapour-proof barrier was installed above the flagstone floor, monitored wall moisture did not increase over the three-year study period. [2]

This does not prove that impermeable floors can never alter moisture conditions in an old building. It does show that the effect should not be assumed as an automatic consequence: the actual wall, ground conditions, drainage and moisture pathways still need to be investigated.

Cyprus - an important counter-example, but not a direct Manx analogue

A monitored traditional building in Cyprus provides valuable counter-evidence. Its stone walls were about 500 mm thick and contained rubble infill. A declining low-level moisture profile was interpreted as rising damp to around 800 mm. [9]

That is important because it confirms that rubble-filled masonry can support ground-derived capillary rise. But the principal stone was an exceptionally porous and absorptive calcarenite. The study reported open porosity of about **42.3%**. By comparison, granite used in controlled British masonry research had open porosity of about **0.87%**. [8][9]



Those figures should not be converted into a simple ratio of capillary performance - pore size and connectivity matter as much as total pore volume - but they make one point very clearly: the Cyprus wall is **not a close hydraulic analogue** for many Manx walls incorporating much denser metasedimentary stone commonly described locally as Manx slate, granite or quartz-rich material.

In such walls, mortar joints, fractures and interfaces may play a proportionately greater role in liquid-water transport than the principal stone blocks themselves. The granite rainfall experiments support precisely that possibility: most moisture transport occurred through the lime-mortar network rather than through the dense granite. [8]

“Rubble wall” is no more a hydraulic specification than “stone wall.”

Two rubble walls, two different outcomes

Bath and Cyprus do not cancel one another out. They show why construction-specific evidence matters. In Bath, water availability did not produce the rise predicted by a homogeneous model. In Cyprus, rising moisture was observed in a rubble wall built from highly absorptive stone, although the observed height was still much lower than a simplified theoretical prediction.

The lesson is not that one study is right and the other wrong. The lesson is that rubble walls are variable systems whose behaviour depends on constituent materials, internal structure, interfaces, voids, water supply and environment.

The wall may have changed since it was built

Historic walls are not frozen in time. Repeated wetting and drying, movement, frost, salt crystallisation, mortar erosion, repointing, leaks, floor replacement, new renders and new plasters can all alter their internal moisture network.

The lime mortar within a 150-year-old wall may remain porous, but the **geometry and continuity of the complete pathway** may no longer resemble the wall as first built.

Wall thickness is not a defence

A thick wall is not automatically protected from rising damp. If sufficient hydraulic continuity and water supply exist, a thick wall can store substantial quantities of moisture. Thickness only makes sense alongside water supply, connectivity, material arrangement and evaporation.




CHAPTER TAKEAWAY

- Rising damp can occur in rubble-filled masonry, but rubble construction does not behave uniformly.
- The Bath study shows that a real 600 mm heterogeneous wall may not behave like an idealised homogeneous capillary model.
- The Cyprus wall is important positive evidence, but its exceptionally absorptive calcarenite is not a close hydraulic analogue for many denser Manx walling stones.
- In dense-stone masonry, mortar, fractures and interfaces may become proportionately more important liquid-water pathways.
- “Stone wall” or “rubble wall” is not, by itself, a hydraulic description.
- In the Bath study, installing a vapour-proof layer over the floor did not measurably increase moisture in the adjacent rubble wall; the proposition that an impermeable floor automatically drives damp up neighbouring walls should therefore be tested rather than assumed.



CHAPTER 5

The surface and the wall behind it



During a survey, we rarely touch the wall core. We touch the finish.

The material being photographed and measured is usually plaster, render or paint - and that distinction matters because the finish may behave very differently from the masonry behind it.

Wallpaper, skim coats and patch repairs may add further layers. What looks like one wall surface can therefore contain several materials and several different moisture histories.

The plaster may be the most continuous material in the wall

Consider a 550 mm rubble wall. Internally, its core may contain irregular stone, old lime mortar, rubble, fines, voids, cracks and hundreds of interfaces. Over that sits perhaps 15–25 mm of plaster.

The plaster is much thinner, but it may be comparatively continuous. This gives us an important contrast: **thick but hydraulically complex wall core** versus **thin but comparatively continuous surface layer**.

Research shows that render can change the pathway

Controlled masonry experiments have shown that a continuous render layer can alter capillary movement through the assembly, providing what researchers described as a bridging surface over the masonry beneath. [4]

The finish was therefore not simply displaying the moisture condition of the underlying wall. It was participating in the moisture movement itself.

The Bath wall gives us an intriguing example

In the Bath/Historic England rubble-wall study, low-level deterioration was observed to the internal plaster even though the monitored core did not show the substantial capillary rise predicted by the theoretical model. The researchers considered it possible that **localised capillary rise had occurred within the plaster itself**. [2]

They did not prove that this was the cause. The importance is the distinction it opens between capillary moisture within the surface finish and capillary rise through the full wall thickness.

The surface may therefore tell a different story from the core

If plaster runs continuously down towards floor level and is in contact with damp material, it can potentially absorb and transport that water. Meanwhile, only a short distance behind it, the rubble core may have a different moisture distribution.

The result could be wet plaster over less-wet or irregularly wet masonry. This matters enormously if all measurements are taken from the surface.

A measurement taken from plaster is first and foremost a measurement of plaster and its immediate surroundings.

The plaster may also have its own history

The wall core in a Victorian building might date from 1870. The plaster may have been repaired in 1920, partly replaced in 1960, skimmed with gypsum in 1985 and patched again in 2010. The surface and the wall behind it can therefore have completely different histories.

Plaster can bridge an existing damp-proof course

Suppose a wall contains an original slate DPC. The masonry above may be successfully isolated from ground moisture, but later plaster carried continuously across the DPC and into contact with damp material below can potentially provide a bypass.



The visible symptom might then resemble “failed DPC”, even though the barrier in the masonry still functions. We will return to this when considering historic damp-proofing.

CHAPTER TAKEAWAY

- Plaster and render can participate in moisture transport; they are not always passive coverings
- A thin but continuous finish may provide a different pathway from a thick, irregular rubble core.
- The moisture condition of plaster need not be identical to the moisture condition deeper within the wall.
- Surface finishes can bridge an otherwise functioning DPC.
- The prevalence of plaster-only capillary pathways in real buildings remains uncertain, so this is a mechanism to investigate rather than assume.



PART THREE - THE SAME SYMPTOM, DIFFERENT JOURNEYS
CHAPTER 6

Low-level damp does not identify its source

The location where moisture appears is not necessarily the location where it entered the building - or even the location where it first became liquid.


Imagine walking into a room and finding peeling paint near the skirting, a tide-like line of deterioration, white salts and elevated moisture-meter readings that decrease with height.

That pattern may be **compatible with rising damp**. But compatible is not the same as confirmed.

Source → Transport → Manifestation

One of the most useful ways to think about dampness is to separate three things.





Source

Where did the water originate? Possibilities include groundwater, rain, a leaking gutter, plumbing, a failed drain, flooding, surface condensation or water vapour condensing within the wall.

Transport

How did the water subsequently move? Possibilities include capillary action, gravity, mortar, cracks, voids, interfaces, plaster, render or several routes together.

Manifestation

Where and how did the moisture finally become visible or measurable? Perhaps at the skirting, around a window, on a chimney breast, behind furniture, within plaster or deep inside the wall.

The place where we see the damp is not necessarily where the water entered the building.

Capillary movement does not automatically mean rising damp

Capillary action is a transport mechanism. Rising damp is a particular combination of ground-derived liquid water plus upward capillary transport.

If rainwater enters high in a wall, moves downward through cracks and is then drawn into plaster by capillary action, capillary transport has occurred - but the problem is not rising damp. If plumbing water reaches the base of a wall and is drawn upwards through plaster, capillary movement again occurs. Still not rising damp.

Once vapour becomes liquid, the physics changes

Interstitial condensation begins with water vapour. If that vapour condenses inside the construction, liquid water now exists within the pore network.

From then on it is subject to the same broad liquid-water processes as water introduced from elsewhere: capillary redistribution, gravity, movement through mortar and interfaces, evaporation and salt transport.

RESEARCH SPOTLIGHT

A known non-ground water source can still produce capillary rise

Following a serious fire at the historic Elleboogkerk in Amersfoort, large quantities of firefighting water accumulated on a concrete floor. Groundwater was also present at the site. Height-and-depth investigation showed some genuine groundwater-derived rising damp at low level, but much of the more extensive wetting was attributed to firefighting water being drawn into the masonry by capillary action. [32]

The case demonstrates two things at once: **capillary transport does not identify the original source**, and proving some genuine rising damp does not prove that rising damp caused all of the moisture present.

Several mechanisms can coexist

Real buildings frequently refuse to provide one neat diagnosis. A wall might simultaneously experience some ground moisture, rain penetration, hygroscopic salts, intermittent condensation and restricted evaporation from a later cement render.

The correct diagnosis may therefore not be “rising damp” or “condensation”. It may be several interacting mechanisms, with one contributing more than another.



Where several mechanisms coexist, the diagnostic question is therefore not only which mechanisms are present, but which are materially influencing the wall's current moisture balance. Demonstrating some ground-derived capillary rise would not, by itself, establish that rising damp explains all of the low-level moisture observed.

CHAPTER TAKEAWAY

- Moisture source, transport mechanism and final manifestation should be considered separately
- Capillary movement can occur with water derived from rain, plumbing, flooding or condensate as well as groundwater.
- Once vapour condenses, the resulting liquid can redistribute through the wall.
- Several moisture mechanisms can coexist in the same construction.
- Low-level moisture is a location in which moisture has manifested; it is not a mechanism.
- Evidence that one moisture mechanism is present does not establish that it is the sole or dominant cause of the wall's condition.



CHAPTER 7

Other routes to low-level moisture

Here is the diagnostic difficulty: several very different moisture sources can end up producing dampness in exactly the same low-level part of a wall.


Current Historic England guidance and the Joint Position Statement both emphasise investigating the whole building and identifying the source of excessive moisture rather than relying on a single familiar pattern. [1][15]

How common is genuine rising damp?

Current Historic England guidance describes rising damp caused by groundwater as fairly uncommon. It cites a Building Research Establishment analysis of 1,500 damp investigations in which rising damp accounted for 4% of cases. [1]

That figure is useful context, not a property-level diagnostic probability. It does not rule rising damp out, and it should not be used to decide what is happening in an individual building. Its value is narrower: low-level dampness has many competing causes, so a diagnosis of rising damp still requires positive evidence for the proposed ground-derived moisture journey.





Rainwater

Traditional buildings on the Isle of Man are exposed to wind-driven rain. Water may enter through defective render or pointing, cracked masonry, window openings, flashings, gutters, downpipes, parapets or chimneys. At low level, rainwater can also splash back from hard paving, concrete or other surfaces and repeatedly wet the wall base, particularly on exposed elevations. [1]



Once inside a thick wall, it need not emerge opposite the point of entry. It may move downwards under gravity, enter more absorbent mortar, spread laterally, follow a crack or void and eventually accumulate much lower in the construction.

RESEARCH SPOTLIGHT

Rain through a dense-stone wall

Controlled rainfall experiments on granite-and-lime-mortar walls found that the granite itself absorbed little water, while the lime-mortar network dominated moisture movement. Lower joints became wetter partly because of downward movement and run-off. [8]

For dense-stone Manx walls, this is a valuable comparator: the stone does not need to absorb uniformly for significant water movement to occur. Mortar, joints, fractures and interfaces may carry much of the liquid.

External ground levels and surface water

Not all ground-associated moisture is rising damp. Raised paths, gardens or driveways can hold water directly against masonry above an original DPC, allowing lateral entry or bridging of a barrier that may still be functioning. Poorly drained ground can also saturate an external face without there being a regional groundwater table immediately beneath the building.

Present external levels should not automatically be assumed to be original. Roads and pavements may have been resurfaced, rear yards concreted or overlaid, paths rebuilt and gardens raised. In late-Victorian Douglas this distinction is especially important because the 1893 regulations required the upper level of ground-floor joists to stand at least six inches above the adjoining footway, street or court, while the DPC was separately required to be at least six inches above adjoining ground. Later changes can therefore consume an originally deliberate vertical separation without any failure of the original barrier itself. [28]

Drains and underground services

A cracked drain, leaking water service, defective gulley or poorly discharged downpipe can provide a persistent local source of water. Capillary rise may genuinely occur from that local saturation, but the first remedial target may be the defective service rather than the wall.

Plumbing

Internal leaks can continue for months without becoming immediately visible. Water entering a floor or wall can migrate considerable distances before emerging. If it reaches the base of absorbent plaster or masonry, subsequent upward capillary movement is entirely possible.

Surface condensation

Condensation can concentrate at low level where floor junctions and external walls are colder, air movement is restricted or thermal bridging is significant. The moisture source is then the indoor atmosphere rather than the ground.



Interstitial condensation

Where vapour condenses within the wall, liquid water is created inside the construction. That liquid can subsequently move under gravity and capillary forces, dissolve salts and emerge at a different location from the original condensation zone.

TC-05 - Understanding Interstitial Condensation examines this process in detail. For the purposes of rising-damp diagnosis, the important point is narrower: in suitable hygrothermal conditions, interstitial condensation can provide a genuine non-ground source of liquid water within a thick wall, after which gravity and capillary redistribution may contribute to a low-level moisture pattern.

RESEARCH SPOTLIGHT

A warm room does not prove a warm wall

Long-term SPAB monitoring placed temperature and relative-humidity sensors through traditional wall constructions and showed that conditions within a wall can differ markedly from those at the room surface. The programme examined actual temperature gradients, dew-point gradients and the margin before local saturation. [36]

Heating history also matters. Becker's dynamic analysis directly compared continuous and intermittent heating and found that heating schedule and wall thermal inertia materially affect internal surface temperatures and condensation risk. [37]

A measured historic-masonry example comes from Krimulda Church in Latvia. During rapid intermittent heating, indoor air warmed much faster than the masonry; researchers recorded very cold wall surfaces and found that calculated envelope temperatures approached dew point during large temperature fluctuations. [38]

These studies do not prove that unexplained low-level damp is interstitial condensation. They demonstrate why a cold massive wall, indoor moisture load and heating pattern can form a physically credible alternative mechanism that deserves to be tested rather than assumed away.

CHAPTER TAKEAWAY

- Rain, drainage defects, plumbing, lateral ground moisture and condensation can all produce dampness at low level.
- In dense-stone masonry, mortar, joints, fractures and interfaces may carry far more liquid water than the principal stone blocks.
- Not all ground-associated moisture is rising damp: raised ground and local saturation can introduce water laterally or create a local water source
- Identifying an alternative source still requires evidence that its pathway fits the pattern found in the building.
- Temperature and heating history can make interstitial condensation a physically credible contributor, but the same evidential standard should be applied to it as to rising damp.



CHAPTER 8

When water travels before we see it



Traditional masonry can store and redistribute water for a long time. The condition we measure today may be the end of a moisture journey that began somewhere else - and perhaps long ago.

As earlier chapters have shown, moisture can be distributed very unevenly through traditional masonry. Dense stone, mortar, cracks, interfaces and finishes may each carry or store different amounts of water.

Gravity and capillarity can act together

Water movement is sometimes described too neatly: rain moves down; rising damp moves up. In reality, both gravity and capillary forces can act on the same body of water.

Evaporation changes the pattern

The moisture pattern visible at a surface reflects a balance between **water arriving** and **water leaving**. A wall receiving modest moisture but drying freely may remain sound. The same wall covered with finishes that restrict drying may retain more moisture and develop deterioration elsewhere.

A wall has a moisture balance

A useful way to think about a traditional wall is to consider all of the moisture entering or forming within it over time, and all of the opportunities available for that moisture to leave. Inputs may include ground moisture, wind-driven rain, leaking services, flooding and condensate. Drying may occur inward, outward or in both directions as liquid water redistributes and evaporates. [1][39]

One short-lived wetting or condensation event may be insignificant if the wall subsequently returns towards equilibrium. Concern increases when repeated inputs occur faster than the construction can recover. A wall that remains slightly wetter at the end of one winter can begin the next wetting season with less drying capacity available.

Now add an external defect that introduces free liquid water, and then reduce evaporation with a dense render, coating or otherwise poorly matched finish. The visible low-level dampness may become the cumulative expression of several mechanisms acting over years rather than the clean signature of one source.

> TREE CASSYN OBSERVATION
>
> **A damp wall does not know our diagnostic labels**
>
> Groundwater, rainwater, condensate and plumbing water may originate in very different places. Once liquid water is within the pore network, however, the same physical processes - capillarity, gravity, storage, evaporation and salt transport - can act upon it.
>
> Over years, several moisture inputs may overlap while later finishes or alterations reduce drying. The low-level pattern found during a survey can therefore reflect the combined moisture history of the wall, not a single textbook mechanism.
>
> The diagnostic task is to reconstruct origin, pathway, timing and relative significance - and then decide which intervention is most likely to improve the wall's moisture balance.

A moisture reading has no timestamp

This is particularly important in thick traditional masonry.

A roof leak may have occurred years ago. A plumbing failure may already have been repaired. A flood may belong to a previous winter. Yet moisture introduced by that event can remain stored and continue to redistribute, especially where later finishes have reduced drying.



Finding moisture today does not establish that water is entering the wall today.

This distinction matters because otherwise we risk interpreting **moisture that is still present** as **moisture that is still entering**.

Cement, gypsum and lime change what happens next

It is tempting to group all later finishes together as “non-breathable”, but their behaviour is different.

Dense cementitious renders and coatings can restrict evaporation through a wall face and can reduce the ability of capillary-active masonry beneath them to dry. They do not necessarily create the original water source; they change the boundary conditions around it. Moisture already within the wall may remain longer, redistribute internally or emerge through other available routes. Historic England guidance warns that inappropriate dense finishes can slow the drying of traditional masonry and trap moisture within the construction. [1]

Gypsum is different. Gypsum plaster can be hygroscopic and reasonably vapour permeable; its difficulty in traditional damp masonry is not simply “low vapour permeability”. It can take up and display moisture reaching the surface, while prolonged liquid wetting and salts can degrade it. It does not necessarily participate in drying in the same way as a compatible lime plaster.

Lime is useful not merely because it is described as “breathable”. Its connected pore structure can absorb moisture, redistribute liquid water by capillary action and release moisture again when drying conditions permit. Hygroscopicity, vapour permeability, capillary transport and wetting tolerance all matter together.

The finish may not be the source of the moisture. It may be the reason the moisture cannot leave by the route it once did.

Salts move with the water

Soluble salts can dissolve into liquid water and travel with it. As water reaches a zone where evaporation can occur, the salts remain and crystallise. That can produce efflorescence, powdering, blistering paint and plaster failure.

Some salts are also hygroscopic, meaning they can take up moisture directly from humid air. A wall can therefore remain electrically “damp” long after the event that originally transported the salts has ended. BRE Digest 245 and SPAB both caution that high electrical readings may be influenced by salts and are not, by themselves, proof of current rising damp. [13][35]

Salt evidence is not the same as salt provenance

Historic England notes that soluble salts in masonry can originate from several sources, including groundwater, decayed biological matter, pollution, road de-icers, sea spray and the building materials themselves. Building use and combustion can add further salt histories. [1]

Groundwater in the UK commonly carries chlorides and nitrates, so their distribution can contribute useful evidence where a ground-derived pathway is being tested. But chloride or nitrate detection is not a source detector in isolation. On the Isle of Man in particular, marine exposure means chloride must be interpreted alongside location, height and depth profiles, wall history, other ions and the building’s moisture pathways. [1]



The classic tide mark - useful, but not compulsory

The familiar horizontal "tide mark" associated with rising damp is best understood as part of the evaporation-and-salt system. Ground-derived water can carry dissolved salts upwards; as evaporation becomes significant, salts accumulate and may leave a distinct line or band.

Its absence does not prove that rising damp is impossible. Salt concentrations vary, finishes may have been replaced, dense coatings can shift or conceal evaporation zones, and some walls may accommodate modest moisture without obvious decoration failure.

But where long-standing, materially significant rising damp is proposed, the absence of visible or material evidence should not simply be ignored. It is another observation to be reconciled with the diagnosis.

TREE CASSYN OBSERVATION

The missing textbook tide mark

In more than ten years of survey work, Tree Cassyn has encountered countless low-level electrical moisture readings and numerous properties previously described as suffering from rising damp. What we have not encountered is the classic, distinct horizontal salt tide mark so commonly illustrated as characteristic evidence.

That does not establish how common or uncommon rising damp is. It does reinforce a diagnostic question: where the characteristic physical evidence is absent, what other evidence supports the proposed ground-derived mechanism?

This is practitioner experience, not a prevalence study, and should not be treated as research evidence.

Moisture has a history

A useful way to think about salts and residual wetting is as part of the wall's **moisture history**. The survey records the present condition; diagnosis tries to reconstruct the history that produced it.

CHAPTER TAKEAWAY

- Gravity, capillarity and evaporation can all influence the final moisture pattern within a wall.
- A moisture reading has no timestamp. Water found today may have entered yesterday, months ago or years ago.
- Dense cementitious finishes can restrict drying; gypsum may absorb and display moisture; lime can participate more fully in moisture redistribution and drying.
- Salts can preserve the signature of earlier wetting and can themselves produce later hygroscopic moisture and high electrical readings.
- A classic tide mark can support a rising-damp interpretation, but its absence is not proof of absence - it is evidence that must be considered.
- The long-term condition of a wall reflects its moisture balance: repeated inputs can accumulate where drying and recovery are insufficient.
- Several different sources can contribute liquid water to the same pore network, so the final low-level pattern may represent a combined moisture history.



PART FOUR - DIAGNOSING THE WALL
CHAPTER 9

From moisture reading to moisture diagnosis

A moisture meter can tell us where to look. It cannot tell us where the water came from.

Few instruments are more closely associated with damp surveys than the handheld moisture meter. They are quick, convenient and, used intelligently, extremely useful.

The trouble begins when the reading is asked to answer a question the instrument does not measure.

A meter can contribute evidence. It cannot, by itself, reconstruct the moisture journey.

This need for complementary evidence is also reflected in a 2026 systematic review of rising-damp diagnostic methods in historic masonry, which found that integrated use of different in-situ, non-destructive and laboratory techniques improves understanding of moisture and salt dynamics and supports more reliable conservation decisions. [21]

What is the instrument actually measuring?

Different instruments operate through electrical resistance, capacitance or related properties. On plaster, brick, stone or mortar, the displayed number is commonly a comparative indication rather than a direct percentage measurement of water by mass.

Historic England's moisture-measurement research emphasises that material type, salts, ageing, weathering and composite construction all affect interpretation. [14]

If a meter displays a high response on plaster, it has detected an electrical condition at that surface. It has not chemically analysed the water and it does not know whether the source was the ground, rain, a pipe, condensate or hygroscopic salt.

That does not make the meter useless

A meter can quickly identify areas warranting closer investigation, compare responses across a room, reveal patterns and help direct more targeted testing. The issue is not whether it should be used. The issue is **what conclusion can reasonably be drawn from its readings**.

A declining profile with height

High readings at floor level followed by progressively lower readings further up the wall are commonly associated with rising damp. There is a sound physical reason why genuine ground-fed moisture may create such a profile.

The difficulty is that the pattern is not unique. A wet plaster pathway, salt concentration, lateral ground contact, a lower cold zone or non-ground water that has accumulated at the wall base can produce similar surface patterns.

A declining low-level moisture profile may be compatible with rising damp. It is not, by itself, confirmation of rising damp.



A surface profile is not necessarily a wall profile

On a 550 mm wall comprising plaster, irregular stone, lime mortar, rubble and voids, the meter has not measured "the wall". It has measured a response at or close to one face of a highly complex construction.

The plaster could be wet while deeper masonry is much drier. A mortar joint could be wet while adjacent stone is dry. Salt-contaminated plaster could give a strong electrical response while containing relatively little free liquid moisture.

A moisture profile measured at the surface is not necessarily a moisture profile of the wall.

When the wall does not look damp

A surprisingly common formulation in property reporting is: **"No visible evidence of dampness was noted; however, high instrument readings confirmed the presence of rising damp."**

The apparent contradiction deserves attention. The absence of visible symptoms does not prove that the wall contains no moisture. But the absence of symptoms is still evidence.

Where a diagnosis proposes a long-standing mechanism of ground-derived water repeatedly entering an historic wall, moving upwards and evaporating from its surfaces, it is reasonable to look for material consequences: changes to plaster and decoration, salt movement, deterioration of moisture-sensitive materials, or supporting evidence within the wall itself.

An electrical reading does not become more diagnostic simply because those corroborating signs are absent. Where the wall appears visually sound, the possibility that the response is being influenced by surface material, salts or another conductive constituent becomes particularly important.

"No visible evidence" and "high electrical readings" are two pieces of evidence to be reconciled - not a negative observation followed by a measurement that automatically overrides it.

What would strengthen a diagnosis?

Useful evidence may include the external building condition, ground levels, drains and rainwater goods, plumbing, wall construction, existing DPCs, surface finishes, moisture by height and depth, salt characteristics, environmental temperature and humidity, and changes following rainfall or over time.

In some cases, targeted gravimetric sampling or other invasive testing may be justified. But not every property needs every available test. The strength of the evidence should be proportionate to the specificity and consequences of the diagnosis being made.

Observation is not diagnosis

Suppose a survey records: **"Elevated electrical readings were recorded to the lower 600 mm of an internal wall."** That is an observation and measurement.

To move from that statement to **"The property is affected by rising damp caused by failure or absence of the DPC"** introduces a source, a transport mechanism and often a failure mechanism - none of which was directly measured by the original surface reading.

Observation → Measurement → Interpretation → Diagnosis



The stages are related, but they are not interchangeable. Something scientific has to happen between the reading and the diagnosis.

Why professional guidance is cautious

SPAB warns explicitly against diagnosing rising damp from high electrical moisture readings alone. BRE Digest 245 likewise says high meter readings are not conclusive and discusses moisture profiling and hygroscopic salts. The Joint Position Statement advocates a whole-building approach rather than reliance on potentially misleading isolated data. [13][15][35]

These positions do not make sense because electrical moisture meters are inherently poor instruments. They make sense because the question **"Is this surface producing a high electrical response?"** is fundamentally different from **"Where did the water come from?"**

A low-level moisture profile is a finding. Rising damp is a diagnosis.

CHAPTER TAKEAWAY

- Electrical moisture meters are valuable reconnaissance tools, but on masonry they commonly provide comparative indications rather than source identification.
- A declining low-level meter profile is compatible with rising damp, but other mechanisms can produce similar surface patterns.
- Salts, finishes and heterogeneous masonry can all influence readings.
- Where there is no visible evidence of long-standing damp, that absence should be reconciled with the instrument response rather than ignored.
- A moisture-meter profile can contribute to a diagnosis; it is not the diagnosis itself.



CHAPTER 10

Following the water

A good damp investigation is, in effect, a reconstruction. We start with the condition we can see and work backwards: what source, pathway and history could reasonably have produced it?

Start with the building, not the damp patch

If elevated readings occur along the bottom of a wall, it is tempting to concentrate immediately on that area. But the source may be elsewhere. The investigation should therefore begin with the building as a whole.

- What is the wall made from, and how thick is it?
- What plaster, render and paint systems are present?
- What happens externally at the corresponding location?
- Are ground levels raised or drainage arrangements poor?
- Where do gutters and downpipes discharge?
- Are drains or plumbing services nearby?
- Is there evidence of previous leakage or flooding?
- Is the wall exposed to wind-driven rain?
- Has the building been altered?
- Is an original physical DPC visible or plausible?
- What are the heating, ventilation and condensation conditions?

The whole-building approach

This is essentially the approach advocated by the 2022 Joint Position Statement. RICS, Historic England and the Property Care Association agreed that traditional buildings should be understood as complete systems and that investigators should seek the source of excessive moisture rather than rely on isolated data. [15]

BS 6576 says something very similar

BS 6576 is often thought of mainly as a standard for installing chemical DPCs. Its title begins with the **diagnosis of rising damp**, and it requires rising damp to be differentiated from other causes before treatment is undertaken. It also addresses solid walls and random rubble-filled walls. [16]

Even a standard devoted partly to chemical DPC installation begins with diagnosis.

Source, pathway and evidence

1. What is the proposed source?

If rising damp is proposed, where is the ground-derived liquid water? It may be groundwater, perched water, saturated soil or another persistent supply at foundation level. But there must be a plausible source.



2. What is the proposed pathway?

How does that water travel through the actual wall construction? In a 550 mm rubble wall the path might involve mortar, stone, rubble, interfaces, cracks, plaster or render.

3. What evidence supports that particular journey?

Does moisture exist only at the plaster surface or through depth? Does it decline with height? Are salts present? Is the deeper masonry wet? Are there external defects that provide a simpler explanation? Does the pattern respond to rainfall or indoor climate? Is a persistent ground-derived liquid-water supply actually plausible?

Evidence can also weaken a diagnosis

Investigation is not simply a search for evidence that supports the first hypothesis. Contradictory evidence matters too. A good diagnostic question is: **What evidence would I expect if my explanation were correct - and what evidence would make me reconsider it?**

Height, depth and time

A vertical profile tells us how conditions change with height. A depth profile tells us how they change from the surface into the wall. Time tells us whether the moisture is stable, seasonal, rainfall-related or still drying from an earlier event.

Under the conditions of a typical single-visit, substantially non-invasive survey, we may not be able to establish whether free liquid moisture exists deep within the wall core. That limitation should be acknowledged rather than concealed by more confident language.

Testing a condensation contribution

Where interstitial condensation forms part of the differential diagnosis, useful boundary-condition evidence can include internal and external air temperature and relative humidity, internal and external wall-surface temperatures, prevailing weather and the reported heating regime. A room that has only recently been heated should not be assumed to have a wall at thermal equilibrium. [36][37][38]

Those measurements do not reveal the exact temperature or relative humidity at a particular depth within a 550 or 600 mm rubble wall. They can, however, strengthen or weaken the physical plausibility of the proposed mechanism. Where direct measurement is impossible, established building physics and hygrothermal modelling can legitimately inform professional judgement, provided the distinction between measured, modelled and inferred conditions remains clear.

TC-05 develops the temperature-gradient, vapour-pressure and saturation concepts more fully. In TC-06 the purpose is diagnostic: condensation should neither be assumed from a cold wall nor dismissed because the internal surface happens to be dry at the time of inspection.

Why now?

If an 1880 wall has broadly the same construction in 2026, the statement “it has no modern DPC” does not explain why excessive dampness has appeared now. In parts of late-Victorian Douglas, it may also be historically wrong to assume that no physical DPC was intended in the first place.



Something may have changed: ground levels, drainage, floors, render, plaster, heating, ventilation, rainwater disposal, groundwater exposure or the wall's ability to dry. A building may originally have had lower external levels, a clear DPC-to-ground separation, ventilated suspended floors and more favourable drainage, then later acquire raised paving, concrete yards, buried airbricks or finishes that alter drying. Some of those changes could make genuine ground moisture newly problematic; others may reveal a different source altogether.

The age of a wall explains how it was constructed. It does not necessarily explain why a moisture problem has appeared now. The useful question is often not simply "What did the building lack?" but "What has changed in the moisture-control arrangement around it?"

When is further investigation justified?

Where uncertainty remains, the extent of further investigation should reflect the condition of the building and the consequences of getting the diagnosis wrong. A visually sound wall with elevated surface readings alone may justify monitoring rather than immediate invasive testing.

Where significant decay, repeated plaster failure or expensive remedial work is proposed, targeted depth investigation, gravimetric sampling, salt analysis or longer-term monitoring may be justified.

What stronger testing can look like

Where rising damp remains a consequential hypothesis, Historic England describes a structured sampling approach rather than random spot testing: internal samples at 250 mm intervals from floor level to 1.5 m, with an additional sample at 2 m as a control, followed by determination of absolute and hygroscopic moisture content. This can help distinguish free liquid water from moisture associated with hygroscopic salts and reduce the risk of missing a salt band. [1]

Historic England also repeats the BRE indication that less than 5% moisture content at the floor/wall junction makes rising damp unlikely. That should be treated as a diagnostic aid rather than a universal material threshold: masonry type, sampling position, salts and construction heterogeneity still matter. [1][35]

A 2026 systematic review of 44 studies reached a compatible methodological conclusion: complementary in-situ, non-destructive and laboratory techniques provide stronger diagnostic evidence than reliance on a single method, because different tools answer different questions about moisture distribution, salts and material behaviour. [21]



CHAPTER TAKEAWAY

- Best-practice guidance starts with diagnosis, not treatment.
- A credible investigation tests a plausible source, a physical pathway and the evidence that connects them.
- Moisture should be considered by height, depth and, where relevant, over time; a single non-invasive visit may leave important questions unresolved.
- Further investigation should be proportionate to the condition of the building and the consequences of the proposed intervention.
- Where condensation is a credible alternative, air and surface temperatures, environmental conditions and heating history can help test plausibility, but they do not directly measure conditions deep within the wall.
- Where invasive investigation is justified, structured height/depth sampling and complementary methods are stronger than isolated spot tests; the purpose is to distinguish free moisture, hygroscopic effects and plausible source pathways.



PART FIVE - THE MANX BUILDING
CHAPTER 11

Does location change the risk?



Rising damp cannot occur without ground-derived liquid water reaching the base of the construction. That water may involve groundwater, perched water, persistently saturated soil or another ground-associated supply.

Geology, superficial deposits and topography matter because they help determine whether, where and for how long that liquid supply is available.

So before asking how high that water might rise, an obvious question follows: how much liquid water is actually available beneath or beside the building?

That question receives surprisingly little attention in many everyday damp assessments, yet water availability is part of the mechanism.

Three separate questions

Is liquid water available?

This concerns groundwater, perched water, saturated soil, seasonal saturation, seepages and persistent local water sources.

What controls that availability?

This concerns geology, superficial deposits, clay layers, permeability, slope, rainfall, drainage, springs and local topography.

What happens when the water reaches the building?

This concerns wall materials, pore connectivity, mortar, interfaces, damp-proofing, evaporation and surface finishes.

Geology and topography do not diagnose rising damp. They modify the plausibility of the required water source.

The Isle of Man is not one groundwater environment

British Geological Survey work shows that groundwater behaviour varies considerably across the Island. Much of the Isle of Man is underlain by highly lithified Manx Group rocks with low bulk porosity and permeability, but groundwater can still move through fractures, fault zones, shallow weathered rock and superficial deposits. Springs and seepages are common in some slope settings. [26]

Hillsides and perched water

On slopes, rainwater infiltrating through soil and superficial deposits can meet a less permeable layer below, collect at the interface and move laterally downslope. A house may therefore sit well above any regional water table yet still experience shallow perched water or seasonal seepage at foundation level.

This is why the phrase **“water table”** can be misleading. What matters to the building is whether liquid water is persistently or periodically available at the wall base.

Distance from a water table matters as well. Historic England notes that in non-saturated soil the upward capillary force in a wall is opposed by suction pressure from the ground; as the separation between the wall base and the water table increases, that opposing suction increases and the risk of sustained rising damp reduces. This does not create a universal cut-off depth, but it reinforces the distinction between simply having ground beneath a wall and having an effective liquid-water supply to it. [1]



The Northern Plain is different

The Northern Plain contains complex glacial and raised-beach deposits of sand, gravel and clay. Clay layers can create shallow discontinuous or perched groundwater, while nearby freely draining deposits behave very differently. [26]

Peel, Castletown and other settings

The Peel Sandstone and the Carboniferous limestone around Castletown provide different groundwater environments again, with fissure flow and differing permeability. None of this means that one town "gets rising damp" and another does not. It means that the water environment cannot reasonably be assumed to be identical across the Island. [26]

> RESEARCH SPOTLIGHT
>
> **Local variability at one Manx site**
>
> A 2025 ground investigation at Cross Vein recorded shallow groundwater in some boreholes at roughly 0.6–1.55 m below ground level, interpreted as perched water, while other boreholes on the same site encountered no water. [27]
>
> The value of the example is not the precise depth. It is the **local variability**: groundwater exposure can change materially over short distances.

Topography changes where water goes

A slope does not change the physics of capillary action inside a brick. It changes where water collects before reaching the brick. Water may move downslope through shallow deposits, collect against an uphill wall, emerge along a spring line or remain perched above a less permeable layer.

Groundwater is not the only ground-derived water source

Wet soil at a wall base might result from naturally shallow groundwater, perched water, rain held above clay, runoff, a leaking drain, a downpipe or water trapped by impermeable paving. The wall responds to the water it receives; diagnosis still needs to identify why that water is there.

A Manx ground-moisture framework

For practical investigation, several layers of information can help test source plausibility: bedrock geology, superficial deposits, topography, springs and seepages, nearby borehole observations, local drainage, ground levels and the building itself.

The aim is **not** to create a property-level "rising damp risk map". It is to ask whether the water source required by the proposed diagnosis is physically credible in that setting.

Before asking how high ground-derived water might rise through a wall, it is reasonable to ask whether a sufficiently persistent liquid-water supply is actually available to enter the wall at all.



CHAPTER TAKEAWAY

- Significant rising damp requires an available source of ground-derived liquid water.
- Geology and topography influence where and how long that water may be available, but they do not diagnose rising damp.
- On the Isle of Man, fractured bedrock, superficial deposits, slope water and perched groundwater create materially different local exposure conditions.
- A regional water table is not the whole story; the relevant question is whether liquid water is persistently or periodically available at this wall.
- Site context is therefore a risk modifier within diagnosis, not a substitute for building-specific evidence.



CHAPTER 12

Was there really no damp-proof course?



A Victorian solid wall is not shorthand for “no DPC”. In later-Victorian Douglas, a physical damp-proof course was not merely available technology: by 1887 it was an express regulatory requirement for new buildings within the Douglas regime. Bridging, bypass and actual barrier failure are therefore different diagnostic possibilities.

There is a familiar assumption about Victorian buildings: old solid wall = no damp-proof course. Sometimes that will be correct, particularly in earlier or unregulated construction. But date, wall type and appearance alone are not enough to establish absence.

Damp-proofing is older than many people realise

Historic England records purpose-designed damp-proofing from the mid-nineteenth century, including vitrified stoneware from 1859, later bituminous products and widespread use of slate. By the late 1870s, damp-proof coursing had entered English building legislation. [24]

The Manx evidence now allows us to go further than saying such details were merely plausible.

Douglas: a physical DPC was required by 1887

Douglas Town Commissioners' July 1887 bye-laws required every wall of a new building to contain a proper damp course of sheet lead, asphalte, slates laid in cement or another durable material impervious to moisture. The DPC was to sit beneath the lowest timbers and at least six inches above adjoining ground. [28]

The 1893 replacement code retained that requirement and added an explicit construction hold-point: the damp course was not to be built upon until approved by the Commissioners or their surveyor. Notice was also required before important concealed work, including damp courses, was covered. [28]

The DPC was only one part of the arrangement

The same 1893 regulations separately addressed damp sites, drainage, floor and ground levels, rainwater, external walls, sub-floor ventilation and occupied-room ventilation. Crucially, the upper level of ground-floor joists in a dwelling had to stand at least six inches above the adjoining footway, street or court. The historical moisture-control strategy therefore combined a barrier with physical separation, drainage and ventilation rather than relying upon the DPC alone. [28]

This matters diagnostically because many surviving streets and yards no longer retain their original geometry. Repeated road resurfacing, reconstructed pavements, concrete yards, overlaid paths, raised gardens and replacement floors can reduce or eliminate the separation the building was designed to have.

Later regulation became more prescriptive

A later Borough code made under powers conferred by the Local Government Consolidation Act 1916 retained the DPC principle but specified materials more closely. The photographed provision expressly recognised sheet lead, rock asphalt, slate, vitrified stoneware and blue brick, excluded tarred felt, required the DPC to remain beneath the lowest timbers, and set it at least four inches above adjoining ground. It also distinguished horizontal DPC provision from vertical moisture protection where lower walls were in contact with ground. The exact adoption or confirmation date of this later pamphlet remains to be verified, so it is used here as a post-1916 comparator rather than assigned a precise year. [28]

A physical DPC can be easy to miss

Slate or other physical DPCs in old stonework may sit within irregular mortar beds, be concealed by render, disappear behind later pointing, be buried by raised ground or only become obvious where part of the wall is



exposed. In a Douglas building of the relevant period, “not visible” should therefore prompt further consideration rather than an automatic assumption of absence.

“No DPC was visible” is not necessarily the same statement as “No DPC exists.”

Failure, bridging and bypass are different things

Even where a physical DPC is present, moisture can appear above it. That does not automatically mean the DPC itself has failed. BRE Digest 245 advises that where a physical DPC exists, outright failure is generally less likely than bridging and surrounding defects. [35]

Raised paths or soil, render carried below the barrier, replacement floors or screeds, and internal plaster can all create routes around an otherwise functioning DPC. In practice it is useful to distinguish no original DPC; a functioning DPC; a locally damaged or discontinuous DPC; and a DPC that is present but bridged or bypassed by later construction.

Plaster makes bypass particularly interesting

Imagine a slate DPC running through the masonry while internal plaster continues down past it into damp material below. The masonry barrier may still function, while the plaster creates a comparatively continuous capillary-active route around it.

The result could still be a low-level declining surface profile. The capillary moisture would be real; the conclusion “failed DPC” would not necessarily be correct. The measured pathway may belong principally to the finish rather than the full wall thickness.

If the DPC really has failed

Physical DPCs are not immortal. Slate can crack, workmanship can be discontinuous and alterations can damage barriers. The historical evidence should therefore change the question, not predetermine the answer: was a DPC required or plausible, can it be identified, does it remain continuous, and have later materials or levels created a route around it?

Another reason to ask “Why now?”

If a physical DPC has remained in place for more than a century and moisture appears only after later changes, reconstructing those changes may be more informative than assuming spontaneous barrier failure. A wall may once have had lower external levels, better sub-floor ventilation and clearer drainage, then later become surrounded by raised paving, concrete yards, buried vents or new finishes. The building fabric may be old; the moisture boundary conditions may be relatively recent.




CHAPTER TAKEAWAY

- In Douglas, a physical DPC was an express regulatory requirement for new buildings by July 1887; the 1893 code retained the requirement and added approval before building-over.
- The 1893 system also deliberately separated ground, DPC and vulnerable floor timbers, so present external levels should not automatically be assumed to be original.
- A regulation establishes intended compliant construction, not the actual condition or survival of every DPC in every building.
- Where a physical DPC exists, distinguish absence, damage/discontinuity, bridging and bypass through later floors, render or plaster.
- “No visible DPC” does not necessarily mean “no DPC”, and “moisture above a DPC” does not necessarily mean “failed DPC”.



PART SIX - TREATMENT
CHAPTER 13

How does a chemical damp-proof course actually work?



Chemical DPC technology is scientifically credible. The harder questions come before and after the chemistry: was rising damp actually established, is there already a physical barrier, and can a new treatment form a sufficiently continuous barrier in this particular wall?

Chemical damp-proof courses are among the most familiar treatments for rising damp. The basic idea is straightforward: if ground-derived liquid water is travelling upwards through a connected pore network, introduce a treatment that interrupts that network sufficiently to reduce further capillary transport.

Check the barrier you may already have

In a later-Victorian Douglas building, the investigation should not begin from the assumption that the original wall necessarily lacked a DPC. Where a physical DPC is visible or historically plausible, the first task is to distinguish true barrier failure from bridging, burial by raised external levels, plaster or render bypass, and defects in adjacent floors or drainage.

Installing a second DPC where the original barrier remains functional but has been bypassed would address a different mechanism from the one actually causing the moisture. Treatment should therefore follow the demonstrated pathway, not merely the age of the building.

A chemical DPC does not simply plug every pore

Many modern systems are based on silanes or siloxanes. These compounds principally alter the relationship between liquid water and pore surfaces, making the treated network much less receptive to capillary uptake rather than filling the wall with an impermeable material.

The objective is to create a sufficiently **continuous treated zone** across the wall that water can no longer readily travel through it from below.

For rising damp to occur, hydraulic continuity matters. For a chemical DPC to stop it, treatment continuity matters too.

Chemical injection can work

Controlled laboratory programmes have demonstrated that chemical treatments can materially reduce capillary water uptake when correctly applied to suitable masonry. [17][19] This guide is therefore not suggesting that chemical DPCs are inherently ineffective.

The useful question is: **under what conditions can we reasonably expect the treatment to form the barrier it is intended to create?**

Regular brickwork gives the treatment a relatively easy task

Regular horizontal mortar beds provide a predictable target. Drilling positions can be consistent and treatment can spread through a reasonably continuous mortar course.

Now imagine a 550 mm rubble wall

The geometry changes completely. Large irregular stones, small packing stones, voids, degraded mortar and later repairs may mean that material introduced through one drill hole does not distribute in the way expected from regular brickwork.

Does the cream reach the far side? Does it enter the relevant capillary-active mortar? Does some disappear into a void? Are untreated pathways left between injection points?



The research recognises the problem

EMERISDA identified masonry regularity, cracks and cavities as important influences on chemical-injection performance. Northern Ireland historic-building guidance similarly notes that voids and deteriorated mortar in rubble walls can cause uneven distribution and may require preparatory grouting to create a more continuous substrate. [18][20]

That raises an interesting question: if a historic rubble wall must first be extensively grouted to make it regular enough for the treatment to spread, how directly can evidence from regular masonry be transferred to the original ungrouted wall?

The same heterogeneity appears twice

Earlier we asked whether the rubble wall possesses enough hydraulic continuity for ground-derived liquid water to rise through it. Now we ask whether the same wall permits sufficiently predictable chemical distribution to interrupt those pathways.

The more complicated the moisture pathway, the more complicated the task of reliably interrupting it may become.

Diagnosis still comes first

Chemical injection is designed to interrupt one specific journey: ground-derived liquid water rising through masonry by capillary action. It does not repair a gutter, a drain, a plumbing leak, interstitial condensation, hygroscopic salts or residual moisture from an old defect. Nor does it correct raised paving or later plaster that is bridging an otherwise functioning physical DPC.

BS 6576 explicitly requires differentiation between rising damp and other causes before treatment. [16]

A chemical DPC is not a below-ground waterproofing system

BS 6576 expressly excludes situations where other forms of treatment are appropriate, including walls below ground level or walls under hydrostatic pressure. Those conditions involve a different water-exposure problem from classical rising damp. [16]

For structures partly or wholly below ground, BS 8102:2022 provides the relevant framework for assessing external water sources and considering drainage, barrier protection, structurally integral watertight construction and drained cavity approaches. A retaining or basement wall in contact with wet ground should therefore not be reduced to a routine “rising damp plus chemical DPC” specification. [40]



CHAPTER TAKEAWAY

- Chemical DPC technology is scientifically credible and can reduce capillary uptake under suitable conditions.
- Before specifying a new DPC, establish whether an existing physical DPC is present and distinguish true failure from bridging or bypass.
- A successful treatment requires sufficient continuity of the treated zone.
- Cracks, voids, irregular mortar and heterogeneous rubble can make that continuity more difficult to achieve.
- Evidence from regular masonry should not automatically be treated as proof of identical performance in every 500–600 mm rubble wall.
- Most importantly, treatment only makes sense once the mechanism it is intended to stop has been reasonably established.
- Walls below ground level or subject to hydrostatic pressure fall outside the normal chemical-DPC treatment scope of BS 6576 and require a below-ground water-ingress assessment, including BS 8102 where applicable.



CHAPTER 14

Injection, replastering and the causation problem

When several treatments are carried out together, a dry-looking wall afterwards can be a good outcome - but a poor experiment. Improvement may be real without telling us which part of the treatment package caused it.

A typical rising-damp treatment may involve chemical injection, removal of plaster, replacement plaster or render and redecoration. Sometimes other measures are included too.

Several things have therefore changed at once. If the wall subsequently looks dry, what has actually been demonstrated?

A successful outcome is not necessarily a successful experiment

Perhaps the chemical DPC stopped rising moisture. Perhaps removal of salt-contaminated plaster removed much of the measured problem. Perhaps the new finish is more resistant to visible salt and moisture damage. Perhaps an earlier source was already drying. Several explanations can coexist.

Researchers encounter exactly this difficulty

EMERISDA highlighted combined treatment as a major problem when evaluating real-world performance. Chemical injection is frequently accompanied by special renders, salt-resistant plasters or other work, making it difficult to isolate the contribution of the DPC itself. [18][19]

A treatment package can succeed without proving which component produced the success.

Should rising-damp treatment always address the plaster?

If long-standing rising damp is genuinely transporting ground-derived water into internal finishes, salt contamination and the condition of the plaster should logically form part of the assessment. Water can dissolve and carry soluble salts towards evaporation zones, where they accumulate and may later remain hygroscopic.

That does **not** mean every rising-damp diagnosis automatically justifies removing every plaster finish. Sound historic lime plaster may be compatible with drying and should not be removed without reason. Nor does every ground-water source necessarily produce severe salt contamination in every finish.

But a report that diagnoses long-standing, materially significant rising damp from high readings in plaster while simultaneously describing that plaster as visibly sound, suitable for retention and requiring no remedial consideration creates a question of internal consistency.

If rising damp is diagnosed, the report should explain what that moisture journey has done to the plaster - and why the plaster should either be retained or removed.

The surface can conceal as well as cure

Dense replacement renders or salt-resistant systems may suppress visible symptoms while the deeper wall remains wet. Northern Ireland historic-building guidance specifically warns that hard replacement render can mask incomplete treatment coverage in rubble masonry. [20]



A dry-looking replacement surface is not necessarily a dry wall

If a new finish is deliberately resistant to salts or liquid moisture, the appearance of that finish cannot by itself prove that free moisture movement through the masonry has stopped.

The diagnosis and treatment can become circular

A familiar chain runs: high meter readings → rising damp diagnosed → DPC + plaster removal → new plaster remains dry → therefore original diagnosis was correct. That reasoning is circular where several interventions occurred together.

The later appearance may be a satisfactory practical outcome, but it is not independent confirmation of the original source diagnosis.

Does the remedy tell the same physical story as the diagnosis?

A useful consistency check is to ask what each intervention is intended to achieve.

- Diagnosis - why is moisture present?
- Chemical DPC - what demonstrated pathway is this intended to interrupt?
- Plaster removal - what evidence shows the existing plaster is damaged or salt contaminated?
- Replacement finish - what moisture behaviour is required from the new material?

Each part of the specification should have its own evidential reason.

CHAPTER TAKEAWAY

- Rising-damp treatment commonly combines injection, plaster removal and replacement finishes.
- Where several interventions occur together, later improvement does not reveal which intervention caused it.
- If long-standing rising damp is diagnosed, the condition and likely salt history of the plaster should form part of the assessment.
- Sound historic plaster should not be removed automatically; equally, a meter-only rising-damp diagnosis with entirely sound retained plaster deserves careful explanation.
- A successful treatment outcome does not automatically validate the diagnosis that preceded it.
- The proposed remedy should tell the same physical story as the diagnosis.



CHAPTER 15

Electro-osmosis and other electrical approaches

Electrical damp treatments are a useful reminder that a real physical mechanism and a convincing product claim are not the same thing. Established electrokinetic mechanisms and far less certain non-contact claims should therefore be separated and assessed on evidence.

Electro-osmosis is a real physical phenomenon

When an electrical potential is applied across certain wet porous materials, interactions between ions, charged pore surfaces and pore water can cause liquid movement. Electro-osmotic transport is well established in soils and porous-material science and has been demonstrated in masonry materials.

That does not automatically establish effective drying in every building. Performance depends on pore structure, conductivity, moisture, salts, electrodes, material properties and applied potential. Franzoni and colleagues found the mechanism physically real but practical masonry drying highly conditional. [17]

The mechanism is real. Its effectiveness as a building treatment is conditional.

Conventional active electro-osmosis requires a circuit

Traditional active systems normally use electrodes installed in or along the masonry together with a grounding or counter-electrode arrangement. An electrical potential is applied through the wet porous material.

That is fundamentally different from a device sitting remotely from the wall and claiming to alter moisture behaviour without forming a comparable electrical circuit through the masonry.

Water does not need its “polarity reversed”

Water molecules are inherently polar. Electro-osmosis does not work by permanently reversing the molecular polarity of water. It involves electrical forces acting upon ions, charged pore surfaces and the liquid in the pore network.

A treatment might conceivably produce an effect even where its marketing explanation is scientifically poor. So two questions should be separated: **Does it produce a measurable effect?** and **Does the proposed explanation accurately describe why?**

RESEARCH SPOTLIGHT

Treated wall versus untreated wall

The EMERISDA programme investigated commercial electro-physical systems using height-and-depth moisture measurements and untreated reference areas. At the Paardenmarkt site in Delft, a historic brick building with high groundwater and genuine rising damp, moisture changes in treated areas after ten months were comparable with changes in untreated reference areas. Effectiveness could therefore not be confirmed over the monitoring period. [33]

This does not prove that every electrical device is ineffective. It shows why reference areas matter: a wall becoming drier after installation is weaker evidence than a treated wall drying **more than a comparable untreated wall** under the same changing conditions.



Less invasive treatment is genuinely attractive

For historic buildings, a reliable non-invasive system would have obvious advantages: little drilling, less plaster removal, less chemical introduction and greater reversibility. That potential benefit means such systems deserve serious investigation rather than automatic dismissal.

It also means claims should ideally be supported by independent measurements, wall-depth data, meaningful monitoring periods and untreated references.

The same evidence discipline applies to every treatment

We should not say “it is electrical, therefore it cannot work”. Nor should we say “the wall became drier afterwards, therefore the device worked”. The questions are the same as elsewhere in this guide: what was measured, how was it measured, what else changed and was there a suitable comparison?

CHAPTER TAKEAWAY

- Genuine electro-osmosis is an established physical phenomenon, but practical masonry drying is conditional.
- Conventional active electro-osmosis should be distinguished from non-contact or broadly “electro-physical” commercial systems.
- Claims about simply reversing the polarity of water are not an adequate scientific explanation of electro-osmosis.
- Controlled field comparisons are much stronger than uncontrolled before-and-after case studies.
- The same evidence-led discipline should be applied to treatments that we apply to diagnosis.



PART SEVEN - BRINGING THE EVIDENCE TOGETHER
CHAPTER 16

When is rising damp the reasonable diagnosis?

In an existing traditional building, rising damp will often be an evidence-backed professional judgement rather than something conclusively proved during one non-invasive visit.

After examining capillary action, wall construction, plaster, salts, alternative sources, ground conditions and measurement techniques, it would be convenient if there were one test that now gave us the answer.

There is not.

In an existing traditional building, rising damp will often remain a **professional diagnosis based on the weight of the available evidence**. That does not make the diagnosis subjective or arbitrary.

Professional judgement is not the absence of evidence. It is the interpretation of evidence that is incomplete, variable and sometimes contradictory.

Proof and professional judgement are not the same thing

In a controlled experiment, researchers can prove that water rose from the base because they supplied it themselves. A domestic survey is usually a single visit, largely non-invasive, undertaken at one point in the seasonal moisture cycle and restricted by existing finishes.

We may therefore be unable to establish directly whether free liquid moisture exists deep in the wall core. That limitation should be recognised. It does not mean the surveyor cannot reach a meaningful conclusion. It means the **certainty of the conclusion should reflect the certainty of the evidence**.

Rising damp becomes more credible when the evidence converges

A diagnosis becomes stronger where several independent observations point towards the same physical journey: persistent ground-water availability; a credible capillary pathway; absent, damaged or bypassed damp-proofing; moisture that is not confined to the surface; a compatible height-and-depth distribution; fabric condition consistent with prolonged wetting; salt evidence; and a lack of more persuasive above-ground sources.

No single one necessarily proves rising damp. Together they may form a strong evidential case.

Presence is not the same as dominance

A wall may contain some genuine ground-derived capillary moisture and still owe much of its deterioration to another source. The Elleboogkerk case discussed in Chapter 6 is a useful example: investigation identified some genuine groundwater-derived rising damp, while much of the more extensive wetting was attributed to firefighting water drawn into the masonry by capillary action. [32]

That distinction matters whenever treatment is source-specific. Before recommending a new DPC, the surveyor should ask not only whether some upward ground-moisture movement is plausible, but whether it is materially responsible for the moisture balance and deterioration that the proposed intervention is intended to correct.



Absence of alternatives is not enough

If no leaking gutter, plumbing defect or condensation problem can be found, that does not automatically prove rising damp. A diagnosis should ideally contain **positive evidence for the proposed mechanism**, not merely the absence of a better explanation.

What would weaken the diagnosis?

Confidence should reduce where the physical story begins to break down: high readings confined to plaster; no visible or material evidence of long-standing damp; a sound DPC with no identified bridge; strong rainfall correlation; a significant plumbing or drainage defect; salts that explain conductivity; known historic wetting and restricted drying; or little evidence of persistent liquid water at the wall base.

None makes rising damp impossible. Each changes the weight of the evidence.

A non-invasive inspection may be unable to say **"rising damp is absent"**. It may still be entirely justified in saying **"rising damp has not been demonstrated by the available evidence."**

That distinction matters because treatment does not require us to prove every alternative impossible. If the evidence does not establish a ground-derived capillary mechanism, there may also be insufficient justification for an intervention designed specifically to stop it.

The language should match the evidence

Observed

What was directly seen or measured.

Consistent with

The finding is compatible with a particular mechanism, but other explanations remain credible.

Considered most likely / probable

The surveyor's professional judgement is that one explanation best accounts for the combined evidence.

Confirmed

Reserved for circumstances where sufficiently direct and compelling evidence supports the mechanism.

The certainty of the language should match the certainty of the evidence.

The same standard applies to alternative diagnoses

This principle should not be used only when challenging rising damp. A report that replaces an unsupported rising-damp diagnosis with an unsupported condensation diagnosis has not improved the investigation. The evidence supporting any alternative conclusion should also be explained.

Does the proposed remedy fit the diagnosis?

As Chapter 14 showed, diagnosis and remedy should tell the same physical story. If long-standing rising damp is proposed, the condition and likely salt history of the finishes should be consistent with that explanation; a meter-only diagnosis made through entirely sound retained plaster therefore deserves careful justification.



Conversely, sound historic lime plaster should not be removed merely because a standard treatment package expects it.

Proportionality matters

If the recommendation is simply to monitor an uncertain area after winter, a degree of uncertainty may be acceptable. If the recommendation is to remove historic plaster, drill and inject a 600 mm rubble wall, install a replacement system and redecorate, the evidential basis should be considerably stronger.

CHAPTER TAKEAWAY

- Rising damp in an existing building will often be an evidence-backed professional judgement, rather than something conclusively proved during one non-invasive visit.
- A strong diagnosis comes from convergence between source, pathway, moisture distribution, fabric condition and contextual evidence.
- The same evidential standard should apply whether the conclusion is rising damp or an alternative mechanism.
- “Rising damp has not been demonstrated” is not the same as “rising damp has been ruled out.”
- The certainty of the report language should match the certainty of the evidence.
- The proposed remedy should be physically consistent with the diagnosis and proportionate to the evidence supporting it.
- Establishing that a mechanism is present is not the same as establishing that it is the dominant cause of the observed dampness.



CHAPTER 17

A practical differential diagnosis

Differential diagnosis sounds technical. In practice it means something simple: keep several credible explanations for the same finding on the table, then test them against the evidence.

The starting observation might be extremely simple: **there is moisture at low level.** The diagnostic task is to determine why.

Begin with what is known

Imagine a Victorian stone house. Electrical readings are elevated from floor level to approximately 600 mm and there is some deterioration to the skirting and plaster.

At this stage we know there is evidence of moisture or conductivity at the lower wall surface. We do **not** yet know where the water came from.

Ground-derived rising damp

This becomes more credible where there is evidence of persistent water at foundation level, a plausible capillary route, a missing or ineffective moisture barrier, a compatible height-and-depth profile and material evidence of repeated wetting and evaporation.

It becomes less persuasive where moisture is largely superficial, an effective DPC is present, another source is clearly identified or persistent ground-water exposure appears improbable.

Can we reconstruct a credible journey from the ground to the observed moisture?

Rain penetration and redistribution

Cracked render, defective pointing, a leaking gutter or wind-driven rain can introduce water much higher in the wall. At low level, splashback from hard paving can repeatedly wet the wall base. Moisture can travel down through cracks and voids, enter absorbent mortar and later redistribute through plaster. Rainfall correlation, exterior defects, orientation, splash patterns and uneven internal distribution can all help test these routes.

High external ground or lateral moisture

Where paving, soil or retaining structures contact the wall at high level, water can enter horizontally. The moisture may still be ground-associated, but the pathway is lateral rather than classical upward rise from beneath the wall.

Below-ground and retaining walls

Where a wall is partly below external ground level, retains a slope or is exposed to hydrostatic pressure, the relevant mechanism may be lateral or pressurised water ingress rather than classical rising damp. BS 6576 identifies such cases as outside the normal chemical-DPC treatment scope; below-ground water exposure should instead be assessed within an appropriate waterproofing and drainage framework. [16][40]

Drainage or plumbing defects

A leaking buried drain or water service can create persistent local saturation. Genuine capillary rise may subsequently occur from that water source, but the critical repair may be the drain rather than a new DPC.



Surface condensation

Low wall surfaces can be colder because of floor junctions, thermal bridges, furniture and restricted air movement. Environmental measurements, surface temperatures, mould patterns and seasonal occupancy can strengthen or weaken this diagnosis.

Interstitial condensation and subsequent redistribution

In suitable hygrothermal conditions, water vapour may condense within the construction. Once liquid exists, it can respond to gravity and capillary forces. The place where condensate eventually becomes visible need not be the place where it originally formed.

Residual moisture from an old defect

A roof leak may have been repaired, a plumbing defect may no longer exist or flooding may belong to a previous year. A thick wall can retain water for a long period, particularly where later finishes restrict drying.

A moisture reading has no timestamp.

Cement, gypsum and changed drying behaviour

Dense cementitious finishes may restrict drying through one face and cause moisture to remain within the wall or redistribute towards other routes. Gypsum behaves differently: it can be hygroscopic and vapour permeable, but may absorb and display moisture reaching the internal surface and is less tolerant of repeated liquid wetting and salts.

Traditional lime construction operates differently again. Its connected pore structure allows it to absorb, redistribute and release moisture as conditions change.

A traditional wall does not need to remain permanently dry. It needs to be able to get wet and then dry successfully.

Hygroscopic salts

A wall may appear damp because salts within the surface finish are taking up moisture from humid air. The salts may have been redistributed during an old moisture event. High electrical readings can therefore involve a present atmospheric moisture source and a historic salt history rather than ongoing ground-derived rise. Salt type can add evidence, but provenance still requires interpretation: chloride, for example, may be associated with groundwater but can also arise from sea spray or other contamination. [1]

Plaster as a separate pathway

A relatively continuous plaster layer can potentially bridge a DPC or transport moisture from a wet floor edge. Where low-level electrical readings occur predominantly within plaster, the possibility that the profile belongs to the finish rather than the whole wall should be considered.

Mixed mechanisms

Perhaps the most realistic outcome in many traditional buildings is that more than one explanation is correct. A wall may be exposed to wind-driven rain, cement rendered externally, affected by some shallow ground moisture, salt contaminated internally and subjected to high winter humidity.



The professional judgement then becomes not simply “which label applies?” but which mechanisms are materially important to the wall’s annual moisture balance, which remain active, and what intervention will improve the building most proportionately?

A practical evidence matrix

Finding	What it may support	What it does not establish by itself
High low-level electrical readings	Moisture/conductivity concentrated near the surface	A groundwater source
Readings decline with height	A low-level moisture influence	Rising damp uniquely
Visible salt band	Salt-bearing moisture has moved and evaporated	A current groundwater source
Wet plaster but drier masonry behind	Surface/plaster pathway or salt effects	Bulk-wall rising damp
Persistent shallow groundwater	A plausible source for rising damp	That the wall actually transports it
Raised external ground	Lateral moisture or DPC bridging	A failed DPC
Roof or gutter defect above	A credible non-ground source	That every damp area derives from it
Rainfall correlation	A rain-associated moisture mechanism	The exact pathway
Cold lower wall / high winter RH	Condensation risk	That condensation caused all deterioration
Known historic leak	Possible residual moisture and salts	That the source remains active
No visible deterioration	Weakens a diagnosis of materially significant long-standing damp	Complete absence of moisture
Sound physical DPC	Weakens unrestricted masonry rise	Absence of bridging
Random rubble construction	Greater pathway uncertainty	Presence or absence of rising damp
Dense stone with lime mortar	Mortar/interfaces may dominate transport	That dense stone makes the wall immune
Intermittent heating, cold fabric and elevated winter vapour pressure	A plausible condensation contribution	That condensation explains all low-level moisture
Several moisture inputs with restricted drying	An unfavourable combined moisture balance	Which source is dominant or still active
Historic physical DPC with modern paving or floor levels raised around it	Bridging, bypass or altered original ground–floor geometry	Failure of the DPC itself



Finding	What it may support	What it does not establish by itself
Rainwater splashback from hard paving	A local low-level rain-associated wetting mechanism	Rising damp or DPC failure
Chloride / nitrate or hygroscopic salt evidence	A history of salt-bearing moisture; potentially a ground-derived pathway in context	Groundwater uniquely - marine, combustion, use and material sources may also contribute
Retaining / below-ground wall or hydrostatic exposure	Lateral or pressurised ground-water ingress requiring below-ground assessment	Classical rising damp or suitability of a chemical DPC

The table does not provide the diagnosis. It does something more useful: it shows why each finding needs interpretation.

The aim is not certainty at any cost

Sometimes the appropriate conclusion will remain: **"The precise moisture mechanism cannot presently be established non-invasively."**

If the wall is stable and there is no urgent decay risk, monitoring may be the most proportionate response. If significant timber decay, plaster failure or expensive remedial work is proposed, further targeted investigation may be justified.

The aim is not to perform every possible test. It is to obtain enough evidence to make a responsible decision.

CHAPTER TAKEAWAY

- Low-level dampness is a finding shared by several possible moisture mechanisms.
- Differential diagnosis asks which physical journey best accounts for the combined evidence.
- Moisture source, transport mechanism and final manifestation should be considered separately.
- Historic moisture and altered drying conditions can remain relevant long after the original defect has disappeared.
- More than one mechanism may be operating at the same time.
- Compatibility is not confirmation.
- The aim is not perfect certainty, but enough evidence to support proportionate professional judgement.
- Where mechanisms overlap, professional judgement should consider their relative contribution to the wall's moisture balance rather than forcing a single label.



Closing Thoughts

The science confirms that rising damp is real. After all the capillary physics, salts, geology and treatment systems, the survey challenge is still the same: does that mechanism best explain the wall in front of us?

Controlled masonry experiments demonstrate that ground-derived water can travel considerable distances upwards through connected pore networks. Natural stone can carry capillary water. Brick walls can carry it. Rubble-filled walls can carry it. Under conditions of abundant water supply and suitable hydraulic continuity, the mechanism is well established.

But that was never the most difficult question.

The difficult question is: Is that what is happening in this wall?

A damp wall has a history

Moisture does not arrive with a label attached. It may have entered from the ground, a leaking gutter, rain driven through an exposed elevation, a damaged drain, a plumbing leak, floodwater or water vapour that later condensed within the construction.

It may then have travelled downwards under gravity, sideways through mortar, upwards through capillary pores, along cracks and interfaces, into plaster and towards whichever surface still allows evaporation. It may have carried salts with it. The defect that originally introduced it may have disappeared years before the survey took place.

A moisture reading records a condition. It does not record the journey that created it.

It also does not record the wall's annual moisture balance. A wall may survive repeated minor wetting for generations where drying is effective, yet become persistently damp when additional water sources appear or later materials reduce evaporation. The present condition may therefore be the accumulated consequence of several small changes rather than one dramatic failure.

Traditional walls make that journey complicated

A historic wall is not a uniform block of porous material. It may contain stone, mortar, rubble, voids, cracks, old repairs, plaster, render and perhaps an original DPC. Each component can interact with moisture differently.

A highly porous calcarenite rubble wall in Cyprus is not hydraulically equivalent to a Manx wall incorporating dense metasedimentary, granitic or quartz-rich stone. A 240 mm laboratory brick wall is not a 550 mm rubble wall. A wet plaster surface does not necessarily demonstrate a wet wall core.

Porosity is not the same as hydraulic continuity.

The building's surroundings matter too

A capillary pathway needs water to supply it. The Isle of Man does not present one uniform ground-moisture environment. Geology, superficial deposits, slope, drainage, groundwater and perched water all influence whether liquid water is persistently available around a building.



None of those conditions diagnoses rising damp. But neither should they be ignored where ground-derived liquid water is proposed as the source.

Before asking how high ground-derived water could rise, first ask whether a persistent liquid supply is actually available to enter the wall.

Instruments are evidence, not answers

Electrical moisture meters remain valuable tools. They allow rapid comparison and can reveal patterns that deserve attention. But the instrument does not know the origin of the water, when it entered the building, whether salts influence the response, or what is happening at the core of a 550 mm wall.

A moisture-meter profile can contribute to a diagnosis. It is not the diagnosis itself.

This is why statements such as **"No visible evidence of dampness was identified; however, high instrument readings confirmed rising damp"** deserve particular caution. The absence of visible evidence is one observation. The meter response is another. The task is to reconcile them.

Best practice makes sense when the science is understood

The Joint Position Statement advises surveyors to understand the building, investigate moisture as part of a whole-building system, avoid reliance on potentially misleading data and exercise professional judgement. BS 6576 requires rising damp to be differentiated from other causes before chemical treatment. Historic England's 2026 practical guide is devoted substantially to understanding what moisture-assessment techniques can and cannot tell us. [1][15][16]

These recommendations are not bureaucratic caution. They follow directly from the building science. If several different moisture journeys can end with the same low-level reading, the journey must be investigated before a treatment designed for one particular journey is specified.

Treatment should follow understanding

Chemical DPCs can work. Electro-osmosis is a genuine physical phenomenon. Drainage improvements can transform water exposure. Lime plaster can support drying. Salt-contaminated finishes may sometimes need replacement.

But none of these should become an automatic response to the word "damp". Intervention should follow the mechanism, and the intervention should be proportionate to both the severity of the problem and our confidence in the diagnosis.

Professional judgement remains essential

Surveyors work with incomplete information. Walls are concealed. Building histories are imperfect. Weather and occupancy change. Invasive investigation is not always desirable or justified.

There will therefore be occasions when the evidence does not permit absolute certainty. That does not remove the need for professional judgement. It makes **transparent professional judgement** more important.

- What did we observe?
- What did we measure?



- What mechanisms could explain those findings?
- Why do we consider one explanation more likely than another?
- What remains uncertain?
- What intervention, if any, is proportionate to that level of confidence?

The central lesson

Perhaps the most important conclusion from all of the research in this guide is remarkably simple:

Low-level moisture is not a mechanism. It is a location in which moisture has manifested.

Rising damp is one explanation. Sometimes it will be the best explanation. Sometimes another moisture source will fit the evidence better. Sometimes several mechanisms will interact. And sometimes the evidence available during a non-invasive inspection will simply not be sufficient to decide conclusively.

That uncertainty should not be disguised by a moisture-meter reading or an overly confident label. Nor should rising damp be dismissed simply because it can be difficult to prove.

It deserves the same treatment as every other building defect: **observe carefully, measure appropriately, understand the building, test the plausible mechanisms, and then exercise professional judgement.**

A low-level moisture profile is a finding. Rising damp is a diagnosis. And something scientific must happen between those two statements.



Glossary of Key Terms

A quick reference to the building-science and diagnostic terms used throughout TC-06.

Capillary Action
Movement of liquid water through fine connected pores or narrow spaces, driven by interaction between the liquid and the pore surfaces.

Capillary Pathway
A sufficiently connected route through a material or wall assembly along which liquid water can move by capillary action.

Capillary Rise
Upward movement of liquid water through a capillary-active material. Capillary rise can occur from several liquid-water sources; rising damp is specifically ground-derived.

Capacitance Moisture Meter
A non-destructive electrical instrument that responds to changes in the dielectric properties of material near the surface. Readings on masonry are normally comparative rather than a direct water-content percentage.

Cementitious Render
A render containing a substantial cement binder. Dense cementitious finishes can be much less accommodating of liquid-water drying than traditional lime finishes.

Damp-Proof Course (DPC)
A physical or chemical barrier intended to interrupt upward capillary movement of ground moisture through a wall.

Dew Point
The temperature at which air with its existing moisture content becomes saturated and condensation can begin.

Differential Diagnosis
A method of considering several credible causes for the same finding and testing each against the available evidence.

Efflorescence
Visible crystalline salt deposits left at or near a surface as salt-bearing moisture evaporates.

Electro-Osmosis
Movement of liquid through a wet porous material under an applied electrical potential. The physical phenomenon is established; building-treatment performance depends on the system and conditions.

Evaporation
The change of liquid water into water vapour at a surface or within a pore network.

Evaporation Zone / Tide Mark
The region in which moisture loss by evaporation and salt deposition becomes concentrated. In some rising-damp cases this can produce a visible horizontal band.

Free Moisture
Liquid water present within a material, distinguished from moisture held from the air by hygroscopic salts or materials.

Gravimetric Moisture Testing
A direct method in which a material sample is weighed, dried and weighed again so that the mass of water lost can be calculated.

Groundwater
Water present below the ground surface within soil, superficial deposits or rock. Its depth and movement can vary seasonally and locally.

Gypsum Plaster
A gypsum-based internal finish. It can be hygroscopic and vapour permeable, but prolonged liquid wetting and salt contamination can cause deterioration.



Hydraulic Continuity
The degree to which a connected liquid-water route continues through pores, joints and interfaces across a material or wall assembly.

Hygroscopic
Able to take up moisture directly from water vapour in the surrounding air.

Hygroscopic Salts
Soluble salts capable of absorbing moisture from humid air. They can make a surface feel or measure damp even without an active liquid-water source.

Interstitial Condensation
Condensation forming within a construction rather than on a visible surface. Once vapour condenses, the resulting liquid can redistribute through the fabric.

Lime Mortar / Lime Plaster
Traditional lime-based materials with connected pore networks that can absorb, redistribute and release moisture, often making them compatible with solid traditional masonry.

Manifestation
The place or form in which moisture finally becomes visible or measurable, which may differ from both its source and its route through the building.

Moisture Source
Where the water originally came from, for example groundwater, rain, plumbing, flooding or indoor water vapour.

Moisture Transport
The mechanism by which moisture moves after entering the construction, including gravity, capillary action, air movement and vapour diffusion.

Perched Groundwater
A local body of groundwater held above the deeper regional water table by a less-permeable layer. It can occur on slopes and vary over short distances.

Permeability
A measure of how readily a material permits a fluid or vapour to pass through it. It is not the same property as porosity.

Pore Connectivity
The extent to which individual pores within a material connect with one another to form routes through which moisture can travel.

Porosity
The proportion of a material that consists of pore or void space. Porosity alone does not establish whether those pores form a continuous capillary route.

Relative Humidity (RH)
A percentage describing how close the air is to saturation at its current temperature. RH changes with temperature even if the actual amount of water vapour remains the same.

Resistance Moisture Meter
An electrical instrument that measures resistance between electrodes or probes. On masonry and plaster its response can be affected by salts and material composition.

Rising Damp
Ground-derived liquid water moving upwards through a wall or other porous construction by capillary action.

Salt Contamination
The presence of soluble salts within masonry or finishes, often left by previous moisture movement. Salts can affect materials and electrical moisture readings.

Silane / Siloxane
Water-repellent chemical families commonly used in modern injected damp-proofing systems to reduce capillary uptake within a treated pore network.

Sorptivity
A measure of how quickly a porous material absorbs liquid water by capillary action, particularly during the early stages of wetting.



Surface Condensation **Condensation that forms on a visible building surface when that surface becomes sufficiently cold relative to the moisture content of the air.**	**Vapour Permeability** The ease with which water vapour can diffuse through a material. It is only one part of moisture behaviour and does not describe liquid-water transport.
Water Vapour **Water in its gaseous, invisible form. If conditions reach saturation within or on a building element, some of that vapour can condense into liquid water.**	**Source → Transport → Manifestation** A diagnostic framework separating where moisture originated, how it moved, and where it finally became visible or measurable.
Moisture Balance **The relationship over time between moisture entering or forming within a construction, moisture being stored or redistributed, and moisture leaving through drying or drainage.**	Thermal Inertia The tendency of a massive material or construction to resist rapid temperature change. Thick masonry can remain cold long after surrounding room air has warmed.
Ground-Derived Liquid Water Liquid water originating in or passing through the ground and available to a building, including groundwater, perched water, saturated soil or other persistent ground-associated supplies.	**Hydrostatic Pressure** Pressure exerted by water at rest against a construction. Below-ground walls exposed to hydrostatic pressure require a different assessment from classical rising damp.



Further Reading & Sources

TC-06 is intended to make a technically complex subject understandable without removing the science. Readers who wish to explore the evidence in greater depth may find the following professional guidance a useful starting point. The research and technical sources cited or consulted in developing the manuscript follow afterwards.

Recommended starting points

Historic England - Assessing Damp in Historic Buildings: A Practical Guide to Investigation and Diagnosis (2026) - The most comprehensive current practical guide to moisture investigation in historic fabric, including the strengths and limitations of measurement techniques.

RICS / Historic England / Property Care Association - Joint Position Statement (2022) - Sets out the whole-building, evidence-led approach and the professional competencies expected when investigating moisture in traditional buildings.

BS 6576:2005+A1:2012 - Diagnosis of rising damp and installation of chemical damp-proof courses - The British Standard specifically addressing rising-damp diagnosis and chemical DPC installation, including the need to distinguish other causes first.

SPAB - What is rising damp? - Accessible conservation guidance explaining the mechanism, common diagnostic pitfalls and the limitations of relying on electrical readings alone.

BRE Digest 245 - Rising damp in walls: diagnosis and treatment (2007) - A concise technical reference on diagnosis, moisture profiles, salts, DPCs and treatment.

EMERISDA research programme / Lubelli, van Hees & Bolhuis (2018) - Useful comparative research on rising-damp treatments and the difficulty of evaluating interventions when several remedial measures are combined.

SPAB Building Performance Survey / ArchiMetrics (Historic England Research Report 231/2020) - Long-term measured evidence on temperature, humidity and moisture behaviour within traditional wall constructions; particularly useful when considering whether condensation and altered drying are physically plausible alternative contributors.

BS 8102:2022 - Protection of below ground structures against water ingress - Relevant where walls or structures are partly or wholly below ground, retain ground, or may be exposed to hydrostatic or lateral water pressure.

BS ISO 22185-1:2021 - Diagnosing moisture damage in buildings and implementing countermeasures: principles, nomenclature and moisture transport mechanisms - A broader standards framework for moisture sources and transport mechanisms.

BS ISO 22185-2:2024 - Diagnosing moisture damage in buildings and implementing countermeasures: assessment of conditions - Describes methods ranging from observation to instrumented condition assessment and reinforces the need to understand the limits of individual methods.

Research and technical sources cited or consulted in this guide

[1] Historic England (2026). Assessing Damp in Historic Buildings: A Practical Guide to Investigation and Diagnosis. HEAG311.

[2] Briggs, K., Ball, R. & McCaig, I. (2022). In-situ measurements of wall moisture in a historic building in response to the installation of an impermeable floor. UCL Open: Environment, 4, e046. DOI 10.14324/111.444/ucloe.000046.

[3] Li, Y. et al. (2021). Construction type influences features of rising damp of blue-brick masonry walls. Construction and Building Materials, 284, 122791. DOI 10.1016/j.conbuildmat.2021.122791.

[4] Guolo, E. et al. (2025). Investigation of capillary rise in brick masonry models under controlled conditions. Construction and Building Materials, 483, 141793. DOI 10.1016/j.conbuildmat.2025.141793.

[5] Congedo, P.M. et al. (2022). Definition of a Protocol for the Experimental Monitoring of Rising Damp in Three Different Masonry Models with Tuff, Carparo, and Lecce Stone. Energies, 15(3), 892.

[6] Derluyn, H., Janssen, H. & Carmeliet, J. (2011). Influence of the nature of interfaces on the capillary transport in layered materials. Construction and Building Materials, 25(9), 3685–3693.

[7] Zhou, X. et al. (2020). Masonry brick–cement mortar interface resistance to water transport determined with neutron radiography and numerical modeling. Journal of Building Physics, 44(3), 251–271.

[8] Fusade, L. et al. (2019). Drying response of lime-mortar joints in granite masonry after an intense rainfall and after repointing. Heritage Science, 7, 38.

[9] Heracleous, C., Ioannou, I., Philokyprou, M. & Michael, A. (2017). Hydrothermal Performance of a Stone Masonry Wall in a Traditional Building in Cyprus. PLEA 2017.



[10] Martínez-Garrido, M.I. et al. (2014). Effect of solar radiation and humidity on the inner core of walls in historic buildings. Construction and Building Materials, 51, 383–394. DOI 10.1016/j.conbuildmat.2013.10.068.

[11] Klõšeiko, P. et al. (2015). Hygrothermal Performance of a Massive Stone Wall with Interior Insulation: An In-situ Study for Developing a Retrofit Measure. Energy Procedia, 78, 195–200.

[12] Floyd, T. (2014). Damp Movement in Rubble Walls. Historic Churches 2014, The Building Conservation Directory, Cathedral Communications.

[13] Society for the Protection of Ancient Buildings (SPAB). What is rising damp? Technical advice.

[14] Viles, H., Zhang, H. & Orr, S. (2022). A Comparative Evaluation of Methods to Monitor Moisture in Historic Porous Masonry Materials. Historic England Research Report 2/2022.

[15] RICS, Historic England & Property Care Association (2022). Investigation of moisture and its effects on traditional buildings – principles and competencies. Joint Position Statement.

[16] BS 6576:2005+A1:2012. Code of practice for diagnosis of rising damp in walls of buildings and installation of chemical damp-proof courses. British Standards Institution.

[17] Franzoni, E. (2014). Rising damp removal from historical masonries: A still open challenge. Construction and Building Materials, 54, 123–136.

[18] Lubelli, B., van Hees, R.P.J. & Bolhuis, J. (2018). Effectiveness of methods against rising damp in buildings: Results from the EMERISDA project. Journal of Cultural Heritage, 31 Supplement, S15–S22.

[19] Franzoni, E., Rirsch, E. & Paselli, Y. (2020). Which methods are suitable to assess the effectiveness of chemical injection treatments in the laboratory? Journal of Building Engineering, 29, 101131.

[20] Department for Communities Northern Ireland, Historic Environment Division. Technical note: Masonry walls.

[21] de Melo, M.E.S. et al. (2026). Diagnostic and characterization techniques for historic masonries with rising damp: a systematic literature review. Journal of Building Pathology and Rehabilitation, 11, 131.

[22] Vereecken, E. & Roels, S. (2014). A comparison of the hygric performance of interior insulation systems: A hot box–cold box experiment. Energy and Buildings, 80, 37–44.

[23] Pender, R. (2016). Water in Permeable Building Materials. The Building Conservation Directory 2016, Cathedral Communications.

[24] English Heritage (2014). Practical Building Conservation: Building Environment. Pender, R., Ridout, B. & Curteis, T. (eds.). Ashgate.

[25] Historic England. Understanding Decay in an Older Home.

[26] Chadwick, R.A. et al. (2001). Geology of the Isle of Man and its offshore area. British Geological Survey Research Report RR/01/06.

[27] Wardell Armstrong (2025). Cross Vein Mine Remediation - Flood Risk Assessment and Drainage Strategy. Isle of Man Planning Portal, planning application 25/90698/B; appeal AP26/0005.

[28] Douglas Town Commissioners / Borough of Douglas. Bye-Laws with respect to New Streets & Buildings, made 4 July 1887 and confirmed by Tynwald 19 July 1887: clause 18 required a physical DPC in every wall of a new building, beneath the lowest timbers and at least six inches above adjoining ground. Replacement By-Laws made 9 November 1893 and approved by Tynwald 17 November 1893: clause 27 retained the DPC requirement and required approval before building-over; clause 28 required notice before concealed work including a damp course was covered. A later Borough code made under powers conferred by the Local Government Consolidation Act 1916 is used as a post-1916 comparator; photographed provisions identify DPC materials including blue brick and address vertical protection to ground-contact walls, but its exact adoption/confirmation date remains to be verified. Primary-source photographs reviewed via Manx National Heritage; 1893 Library Ref. F71/5.

[29] d'Ambrosio Alfano, F.R., Palella, B.I. & Riccio, G. (2023). Moisture in historical buildings from causes to the application of specific diagnostic methodologies. Journal of Cultural Heritage, 61, 150–159.

[30] Falchi, L. et al. (2018). Rising damp in historical buildings: A Venetian perspective. Building and Environment, 131, 117–127.

[31] Schellen, H.L. et al. (2015). The use of COMSOL to explore flooding and rising water problems related to heritage: case study St. Catherine's Chapel, Lemiers, The Netherlands. COMSOL Conference 2015.

[32] Lubelli, B. & van Hees, R.P.J. (2021). Vochtschade na brand: De casus van de Elleboogkerk in Amersfoort. WTA Nederland-Vlaanderen.



[33] Desarnaud, J., Vanhellemont, Y., Lubelli, B. & de Bouw, M. (2021). Effectiveness of electromagnetic and electro-osmosis methods for the treatment of rising damp. ICMB21.

[34] Mahato, C. et al. (2026). Impact of Moisture-Related Phenomena on the Mechanical Performance and Deterioration of Historic Masonry: A Systematic Literature Review. International Journal of Architectural Heritage. DOI 10.1080/15583058.2026.2636749.

[35] Trotman, P. / BRE (2007). Rising damp in walls – diagnosis and treatment. BRE Digest 245 (DG 245).

[36] ArchiMetrics Ltd (2020). SPAB Building Performance Survey 2019 - Final Report May 2020. Historic England Research Report 231/2020.

[37] Becker, R.B. (1993). Effects of heating patterns on internal surface temperatures and risk of condensation. Building and Environment, 28(3), 333–345. DOI 10.1016/0360-1323(93)90038-5.

[38] Metals, M., Lesinskis, A., Borodinecs, A. & Turauskis, K. (2023). Preliminary Study on Indoor Air Temperature and Moisture Behaviour in 13th-Century Churches in Latvia. Sustainability, 15(18), 13965. DOI 10.3390/su151813965.

[39] Historic England (2025). Properties of Traditional Building Construction. Guidance on the coupled movement, storage and release of moisture and heat in traditional permeable construction.

[40] BS 8102:2022. Protection of below ground structures against water ingress - Code of practice. British Standards Institution.

[41] BS ISO 22185-1:2021. Diagnosing moisture damage in buildings and implementing countermeasures - Part 1: Principles, nomenclature and moisture transport mechanisms. British Standards Institution.

[42] BS ISO 22185-2:2024. Diagnosing moisture damage in buildings and implementing countermeasures - Part 2: Assessment of conditions. British Standards Institution.



About the Tree Cassyn Building Science Series

The Tree Cassyn Building Science Series provides practical, evidence-led guidance on the behaviour, maintenance and repair of traditional buildings on the Isle of Man.

Tree Cassyn is an independent Isle of Man firm specialising in damp, timber and moisture investigations, using a diagnostic, evidence-led approach informed by established professional guidance and relevant British Standards.

Each guide introduces one aspect of building performance in accessible terms, drawing upon the recurring construction details and moisture patterns encountered during Tree Cassyn investigations.

IMPORTANT NOTE

This publication provides general educational guidance. Traditional buildings vary considerably, and similar-looking symptoms may arise from different causes. Repairs should be based upon an investigation of the individual building rather than upon general descriptions alone.

TREE CASSYN

DAMP · TIMBER · MOISTURE INVESTIGATIONS

ISLE OF MAN

© Tree Cassyn 2026. All rights reserved.

First Edition | 2026 | Version 1.2

This publication may be downloaded, retained and shared in its original, unaltered form for personal and educational purposes. No part of this publication may be reproduced, modified, rebranded, republished or used for commercial purposes without the prior written permission of Tree Cassyn.

